





report date: 2024-03-29

## General information

Make	TOYOTA
Model	PRIUS VVT-I ICON TECH
Colour	Grey
Year of manufacture	2018
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	1 speed CVT

## Engine & fuel consumption

Power	98 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	80.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	82 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history

## Entry 1

Date 2022-07-23

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$			
10.71	$\alpha$	h	sto	rv
101	( ) I		510	II V
	•			. ,

MOT expiry date	2025-02-07
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #7	2024-02-08 09:44
MOT test number	985608905525
Result	<b>✓</b> Passed
Next expiry date	2025-02-07

MOT #6	2023-08-08 08:56
MOT test number	285063270809
Result	✓ Passed

MOT #5	2023-02-09 09:14
MOT test number	330014060601
Result	✓ Passed
Minor Windscreen wiper blade defective both front rubbers split (3.4 (b) (i))	

MOT #4	2022-08-11 10:36
MOT test number	648871167310
Result	✓ Passed

MOT #3	2022-06-24 10:18
MOT test number	437807855887
Result	✓ Passed
Advice Full under body shields fitted	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #1** 2021-05-25 08:13 **MOT** test number 134530995650 Result **X** Failed **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened INNER SIDE (1.1.14 (a) (ii)) Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii)) Fail Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	7 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	59
Band	D
First licence fee (12 months)	£ 120,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	
*********	
*************	
THE STATE OF THE S	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK NK
Placin since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-06-21
Last registration	2024-02-08
Complete history	See info



Registration #1	2018-06-21	17 mi
Registration #2	2021-05-25	63.361 mi
Registration #3	2021-05-25	63.371 mi
Registration #4	2022-06-24	76.986 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1760 mm
Height	1475 mm
Length	4330 mm
Wheel base	2600 mm
Kerb weight	1415 kg
Max. allowed weight	1815 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

**Engine number** 

2ZRV768317