



report date: 2024-03-29

## General information

Make	VOLVO
Model	V60 D3 R-DESIGN NAV
Colour	Gold
Year of manufacture	2015
Top speed	130 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	150 BHP
Max. torque	320 Nm at 3.000 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	76.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





## Internet history

### Entry 2

Date	2021-07-08
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date	2021-07-06
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-03
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	5

MOT #7	2023-08-03 14:06
MOT test number	816861163497
Result	✓ Passed
Next expiry date	2024-08-03
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #6	2022-08-04 11:12
MOT test number	276808093960
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge WORN ON INNER & OUTER EDGES & CLOSE TO LIMIT (5.2.3 (e))
Advice	ENGINE COVER & UNDER TRAYS & OUTER SILL COVERS FITTED
Advice	Offside Front Tyre worn close to legal limit/worn on edge WORN ON INNER & OUTER EDGES (5.2.3 (e))

**MOT #5**

2022-07-28 10:15

**MOT test number**

877092146361

**Result**

✗ Failed

**Fail**

Central Rear Brake hose ferrule excessively corroded OFF SIDE (1.1.12 (f) (i))

**Fail**

Offside Rear Lower Suspension arm pin or bush excessively worn TRAILING ARM FRONT BUSH (5.3.4 (a) (i))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge WORN ON INNER &amp; OUTER EDGES &amp; CLOSE TO LIMIT (5.2.3 (e))

**Advice**

ENGINE COVER &amp; UNDER TRAYS &amp; OUTER SILL COVERS FITTED

**Fail**

Central Rear Brake hose ferrule excessively corroded NEAR SIDE (1.1.12 (f) (i))

**Fail**

Nearside Rear Lower Suspension arm pin or bush excessively worn TRAILING ARM FRONT BUSH (5.3.4 (a) (i))

**Fail**

Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure MISSHAPED &amp; UNEVEN (5.2.3 (d) (ii))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge WORN ON INNER &amp; OUTER EDGES (5.2.3 (e))

**MOT #4**

2021-07-31 14:13

**MOT test number**

443336566455

**Result**

✓ Passed

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3**

2020-07-17 13:59

**MOT test number**

233242044240

**Result**

✓ Passed

**Advice**

Nearside Rear Brake pad(s) wearing thin close to limit (1.1.13 (a) (ii))

**Advice**

Offside Front Brake pad(s) wearing thin close to limit (1.1.13 (a) (ii))

**MOT #2**

2019-07-12 10:25

**MOT test number**

136663543986

**Result**

✓ Passed

**Advice**

Child Seat fitted not allowing full inspection of adult belt





MOT #1	2018-07-24 12:01
MOT test number	987026239138
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
3 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	3 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2015-05-29
Current registration	 
Plate since	2015-05-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-31
Last registration	2023-08-03
Complete history	<a href="#">See info</a>



Registration #1	2015-07-31	20 mi
Registration #2	2018-07-24	37.991 mi
Registration #3	2019-07-12	48.448 mi
Registration #4	2020-07-17	59.404 mi
Registration #5	2021-05-20	75.277 mi
Registration #6	2022-05-20	91.150 mi
Registration #7	2023-05-20	107.023 mi
Registration #8	2024-05-20	122.896 mi
Registration #9	2025-05-20	138.769 mi
Registration #10	2026-05-20	154.642 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1631 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1270863
---------------	---------