



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 T6 R-DESIGN NAV AWD
Colour	Blue
Year of manufacture	2013
Top speed	155 mph
0 - 60 mph	5.8 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	300 BHP
Max. torque	440 Nm at 2.100 rpm
Engine capacity	2.953 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	38.7 mpg
Consumption combined	28.5 mpg
CO2 emission	231 g/km
CO2 label	L





Internet history

Entry 2


Date	2022-08-23
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-06-02
Pictures	14
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)



## MOT history

MOT expiry date	2024-11-15
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #10	2023-11-16 16:14
MOT test number	385343347974
Result	✓ Passed
Next expiry date	2024-11-15

MOT #9	2022-11-04 16:01
MOT test number	888359404436
Result	✓ Passed

MOT #8	2021-06-18 15:32
MOT test number	501672109001
Result	✓ Passed

MOT #7	2020-07-02 07:45
MOT test number	301686383394
Result	✓ Passed

MOT #6	2020-07-01 13:40
MOT test number	166644292792
Result	✗ Failed

**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))

**MOT #5** 2019-05-01 08:11**MOT test number** 197499995716**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brake disc worn, but not excessively X2 (1.1.14 (a) (i))**MOT #4** 2018-04-24 11:02**MOT test number** 494973337803**Result** ✓ Passed**MOT #3** 2018-04-24 11:02**MOT test number** 760006218921**Result** ✗ Failed**Pass with rectification** Offside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)**MOT #2** 2017-04-10 11:44**MOT test number** 799928869038**Result** ✓ Passed**Advice** Nearside Rear tyre wall cut**Advice** Nearside Front tyre wall cut**Advice** Offside Rear tyre wall cut**MOT #1** 2016-04-26 09:14**MOT test number** 350959320169**Result** ✓ Passed**Advice** Rear both tyre wall cut**Advice** Nearside Front tyre wall cut



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
15 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	15 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-02
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2013-05-02	10 mi
Registration #2	2016-04-26	30.794 mi
Registration #3	2017-04-10	39.396 mi
Registration #4	2018-04-24	46.805 mi
Registration #5	2018-04-24	46.805 mi
Registration #6	2019-05-01	55.667 mi
Registration #7	2020-07-01	63.585 mi
Registration #8	2021-05-20	75.277 mi
Registration #9	2022-05-20	85.277 mi
Registration #10	2023-05-20	95.277 mi
Registration #11	2023-05-20	105.277 mi
Registration #12	2023-05-20	115.277 mi
Registration #13	2023-05-20	125.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1736 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	28031303065