CAR CHECK

UK FY06VXF

report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Silver
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	313 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.7 mpg



Internet history

Entry 9

Date	2022-02-06
Pictures	19
Listing price	View report

source: autotrader.co.uk

Entry 8

Date	2021-12-07
Pictures	19
Listing price	View report

source: autotrader.co.uk

Entry 7

Date	2021-11-06
Pictures	19
Listing price	View report

source: autotrader.co.uk

Entry 6

Date	2021-10-16

Pictures	19
Listing price	View report

source: autotrader.co.uk

Entry 5

Date	2021-09-29
Pictures	19
Listing price	View report

source: autotrader.co.uk

Entry 4

Date	2021-09-11
Pictures	19
Listing price	View report

source: autotrader.co.uk

Entry 3

Date	2021-07-30
Pictures	19
Listing price	View report

source: autotrader.co.uk

Entry 2

Date	2021-07-07
Pictures	19
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-06-10
Pictures	19
Listing price	View report

source: autotrader.co.uk

MOT history

MOT #20	2023-01-26 13:59
MOT test number	992750640693
Result	✓ Passed
Next expiry date	2024-02-01

Advice General corroded

MOT #19	2022-02-02 16:52
MOT test number	114689707119
Result	✓ Passed

MOT #18	2021-01-21 12:44
MOT test number	307548926675
Result	✓ Passed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-01-20 10:28
MOT test number	630058775650
Result	✗ Failed

MAJOR Nearside Front Inner Suspension rod ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Inner Suspension rod ball joint excessively worn (5.3.4 (a) (i))

MOT #16	2020-01-28 12:18
MOT test number	684188344291
Result	✓ Passed

MOT #15	2020-01-27 13:08
MOT test number	409616427207
Result	✗ Failed

MAJOR Nearside Front Lower Track rod end ball joint has excessive play (2.1.3 (b) (i))

MAJOR Offside Front Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

MAJOR Offside Front Lower Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #14	2019-01-19 08:49
MOT test number	500693847624
Result	✓ Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13	2019-01-16 11:16
MOT test number	422784926646
Result	✗ Failed

Advice Nearside Steering linkage ball joint has slight play track rod end (2.1.3 (b) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement upper wishbone (5.3.4 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MAJOR Offside Steering rack has excessive free play detected at the steering wheel (steering rack fitted) track rod end (2.3 (a) (i))

MAJOR Nearside Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MAJOR Rear Brake pipe excessively corroded twin rear pipes (1.1.11 (c))

MAJOR Oil leaking excessively from transmission main sump area (8.4.1 (a) (i))

MOT #12	2018-01-30 16:30
MOT test number	358110119968
Result	✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #11	2018-01-26 17:05
MOT test number	586376524523
Result	✗ Failed

Fail Nearside Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)

Advice Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice Nearside Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice Play in steering rack inner joint(s)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10	2016-10-24 12:00
MOT test number	592187909435
Result	✓ Passed

MOT #9	2016-10-24 12:00
MOT test number	685720407474
Result	✗ Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively replaced wiper blade. (8.2.2)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively replaced wiper blade. (8.2.2)

MOT #8	2015-10-20 13:41
MOT test number	864816236967
Result	✓ Passed

Advice Nearside Steering system has slight free play detected at steering wheel (2.2.A.1b)

Advice Offside Steering system has slight free play detected at steering wheel (2.2.A.1b)

MOT #7	2015-03-12 13:04
MOT test number	676271675029
Result	✓ Passed

Notice Play in steering rack inner joint(s)

Notice Both front tyres have slightly low tread on edges

Advice Brake pipe slightly corroded (3.6.B.2c)

MOT #6	2014-03-12 11:01
MOT test number	195461874434
Result	✓ Passed

Notice Play in steering rack inner joint(s)

MOT #5	2013-03-13 11:57
MOT test number	175042573459
Result	✓ Passed

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

Notice Play in steering rack inner joint(s)

MOT #4	2012-03-22 11:30
MOT test number	707652782026
Result	✓ Passed

Notice Play in steering rack inner joint(s)

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

Notice Nail in nearside rear tyre

MOT #3	2011-03-10 09:47
MOT test number	788619561038
Result	✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Front wipers split at ends

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

MOT #2	2010-03-25 10:57
MOT test number	334544080070
Result	✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-03-04 15:07
MOT test number	600163369053
Result	✓ Passed

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report here for more information.

More info

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ [illegible]
Auction value	£ [illegible]
Average private trade value	£ [illegible]

More info >

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here.

[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]

More info

Plate changes

See in this check if this KIA had different number plates.

Number of plates	[illegible]
Current registration	UK [illegible]
Plate since	[illegible]
Current registration	UK [illegible]
Plate since	[illegible]

More info

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report here and check if this KIA is financed.

Finance company	[illegible]
Date of agreement	[illegible]
Agreement type	[illegible]
Agreement term	[illegible]
Agreement number	[illegible]
Contact info	[illegible]

More info >

Mileage check

Odometer	In miles
Mileage registrations	30
First mileage registration	2006-03-28
Last registration	2023-01-26
Complete history	See info



Registration #1	2006-03-28	22 mi
Registration #2	2009-03-04	19.523 mi
Registration #3	2010-03-25	26.570 mi
Registration #4	2011-03-10	32.822 mi
Registration #5	2012-03-22	38.693 mi
Registration #6	2013-03-13	45.847 mi
Registration #7	2014-03-12	53.514 mi
Registration #8	2015-03-12	59.443 mi
Registration #9	2015-10-20	63.306 mi
Registration #10	2016-10-24	78.470 mi
Registration #11	2016-10-24	78.470 mi
Registration #12	2018-01-26	88.022 mi
Registration #13	2018-01-30	88.190 mi
Registration #14	2019-01-16	93.333 mi
Registration #15	2019-01-19	93.357 mi
Registration #16	[redacted]	[redacted]
Registration #17	[redacted]	[redacted]
Registration #18	[redacted]	[redacted]
Registration #19	[redacted]	[redacted]
Registration #20	[redacted]	[redacted]
Registration #21	[redacted]	[redacted]
Registration #22	[redacted]	[redacted]
Registration #23	[redacted]	[redacted]
Registration #24	[redacted]	[redacted]
Registration #25	[redacted]	[redacted]
Registration #26	[redacted]	[redacted]

Registration #27	[illegible]	[illegible]
Registration #28	[illegible]	[illegible]
Registration #29	[illegible]	[illegible]
Registration #30	[illegible]	[illegible]

More info >

Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	[redacted]
S0482	[redacted]
S0501	[redacted]
S0566	[redacted]
S0567	[redacted]
S0569	[redacted]

View the complete KIA factory list for this vehicle here.

More info >

Safety ratings

NCAP rating	★★★★☆
Video	see crash video

Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2079 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB5840937