





report date: 2024-03-28

### General information

Make	FORD
Model	FOCUS C-MAX ZETEC 115
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	115 BHP
Max. torque	280 Nm at 1.900 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	143 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-10-15

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

### MOT history

MOT expiry date	2023-10-10
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	13

MOT #16	2024-04-18 13:27
MOT test number	612568836249
Result	<b>X</b> Failed
Fail Offside Rear Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Minor Indicator tell-tale inoperative (4.9.1 (a) (i))	
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Minor Hazard warning tell-tale is not a flashing light (4.9.2 (a))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #15	2022-10-07 11:	35
MOT test	<b>number</b> 7442288537	84
Result	✓ Pass	ed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Advice Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number
745237478528

Result

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2021-10-11 11:52 **MOT test number** 300613313097 Result ✓ Passed **MOT #12** 2020-11-25 11:23 **MOT test number** 802272862209 Result ✓ Passed MOT #11 2019-12-02 11:11 **MOT** test number 108557310039 Result ✓ Passed

MOT #10		2018-10-31 15:45
MOT test	number	412646433104
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Child Seat fitted not allowing full inspection of adult belt x 2	

CarCheck.co.uk page 4/13



report date: 2024-03-28

**MOT #9** 2018-10-31 09:00 **MOT** test number 524520045638 Result × Failed Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Advice** Child Seat fitted not allowing full inspection of adult belt x 2 Fail Offside Front All direction indicators incorrect colour (4.4.3 (a)) Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Offside Headlamp aim too high (4.1.2 (a)) Fail Nearside Front All direction indicators incorrect colour (4.4.3 (a)) Oil leak, but not excessive (8.4.1 (a) (i)) Advice **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8

MOT test number

690983830626

Result

✓ Passed

MOT test number

452402365919

Result

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Offside Front tyre worn on edges

Advice Nearside Front worn on edges

Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

 MOT #6
 2016-09-23 09:56

 MOT test number
 958334914062

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5	2015-09-17 12:55
MOT test number	360849687579
Result	✓ Passed
MOT #4	2014-09-22 16:06
MOT test number	458855364220
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

MOT #3	2013-09-23 15:24
MOT test number	368836663496
Result	✓ Passed
MOT #2	2012-09-25 14:45
MOT test number	419569762221
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2011-09-27 10:40
MOT test number	769150871284
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax expired: 20 February 2023

## X MOT

Expired: 10 October 2023

Tax status	Expired at 20 February 2023
Days left	434 days too late
MOT expiry date	10 October 2023
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
HARMAN CONTRACTOR CONT	
************	
***************************************	
***************************************	
	More info >
Plate changes	
Coo in this shook if this FORD had different number plates	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	UK NEZ
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-18
Last registration	2024-04-18
Complete history	See info



Registration #1	2008-09-18	6 mi
Registration #2	2011-09-27	33.077 mi
Registration #3	2012-09-25	42.553 mi
Registration #4	2013-09-23	51.462 mi
Registration #5	2014-09-22	58.244 mi
Registration #6	2015-09-17	66.225 mi
Registration #7	2016-09-23	75.169 mi
Registration #8	2017-09-28	85.345 mi
Registration #9	2017-09-29	85.345 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1491 kg
Max. allowed weight	1995 kg

### Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	age 13/13

Number of axles 2

**Engine number** 8E56053