





report date: 2024-03-28

General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Grey
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg



CarCheck.co.uk page 1/10



FP10KLU

report date: 2024-03-28

MOT history

MOT #13 2022-04-27 14:45

MOT test number 923035116006

Result ✓ Passed

Next expiry date 2023-04-26

Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12 2021-03-08 09:44

MOT test number 145517995419

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2021-03-01 12:05

MOT test number 917728916028

Result X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Rear Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 2/10



FP10KLU

report date: 2024-03-28

MOT #10 2021-01-22 14:40 **MOT** test number 150535252271 Result × Failed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Fail Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9 2019-07-23 09:39
MOT test number 818335102872
Result ✓ Passed

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7	2017-05-29 10:09
MOT test number	981877287755
Result	✓ Passed

CarCheck.co.uk page 3/10



MOT test number

Pass with rectification

Result

FP10KLU

report date: 2024-03-28

465015303142

X Failed

MOT #6		2016-04-30 12:02
MOT test number		279004952701
Result		✓ Passed
MOT #5		2015-05-05 16:35
MOT test number		298785625411
Result		√ Passed
MOT #4		2014-05-07 09:47
MOT test number		219047024157
Result		√ Passed
MOT #3		2014-05-07 09:47
MOT test number		495597224142
Result		X Failed
Pass with rectification	Nearside Front Headlamp aim too high (1.8)	
Pass with rectification	Offside Front Headlamp aim too high (1.8)	
MOT #2		2013-04-15 14:15
MOT test number		188025403140
Result		✓ Passed
MOT #1		2013-04-15 14:15

CarCheck.co.uk page 4/10

Nearside Rear Stop lamp not working (1.2.1b)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

FP10KLU

report date: 2024-03-28

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

about of pliates

faste since

See in this check if this FORD had different number plates.

THE STATE OF THE S

NK NK

More info >

CarCheck.co.uk page 7/10



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-06-25
Last registration	2022-04-27
Complete history	See info



2010-06-25	13 mi
2013-04-15	54.814 mi
2014-05-07	61.660 mi
2015-05-05	72.301 mi
2016-04-30	83.132 mi
2017-05-29	94.867 mi
	11.777 es
	2013-04-15 2014-05-07 2015-05-05 2016-04-30

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 10/10

Engine number

AU21080