



General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG
Colour	White
Year of manufacture	2013
Top speed	137 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	130 kW / 177 HP / 175 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-15
Pictures	27
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-24
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	4
Total items failed	4

MOT #10	2023-08-09 15:12
MOT test number	841633637021
Result	✓ Passed
Next expiry date	2024-08-24

MOT #9	2023-08-01 11:38
MOT test number	279269096701
Result	✗ Failed
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #8	2022-07-29 14:49
MOT test number	972490373534
Result	✓ Passed

MOT #7	2021-08-25 13:23
MOT test number	543546403299
Result	✓ Passed

**MOT #6** 2020-11-16 09:59**MOT test number** 587958904090**Result** ✓ Passed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2019-11-11 15:56**MOT test number** 992010104181**Result** ✓ Passed**MOT #4** 2019-11-11 15:56**MOT test number** 242227809606**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Pass with rectification** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #3** 2018-11-21 16:16**MOT test number** 459997139011**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #2** 2017-11-22 16:04**MOT test number** 225186141077**Result** ✓ Passed**MOT #1** 2016-11-14 11:44**MOT test number** 825067282475**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	24 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-26
Last registration	2023-08-09
Complete history	See info



Registration #1	2013-11-26	14 mi
Registration #2	2016-11-14	13.714 mi
Registration #3	2017-11-22	16.288 mi
Registration #4	2018-11-21	18.489 mi
Registration #5	2019-11-11	20.899 mi
Registration #6	2019-11-11	20.899 mi
Registration #7	2019-11-11	20.899 mi
Registration #8	2019-11-11	20.899 mi
Registration #9	2019-11-11	20.899 mi
Registration #10	2019-11-11	20.899 mi
Registration #11	2019-11-11	20.899 mi
Registration #12	2019-11-11	20.899 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1581 kg
Max. allowed weight	2110 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CFG517648