



report date: 2024-03-28

General information

Make	SMART
Model	FORTWO COUPE PASSION MHD
Colour	White
Year of manufacture	2010
Top speed	90 mph
0 - 100 km/h	13.7 seconds
0 - 60 mph	13.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 2.800 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	61.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	65.7 mpg
CO2 emission	98 g/km
CO2 label	A





## Internet history

### Entry 4

Date 2021-12-07

Pictures 11

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3

Date 2021-10-01

Pictures 11

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date 2021-07-20

Pictures 11

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1


Date 2021-05-24  
CarCheck.co.uk

Pictures

11

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-11-26
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	19
Total items failed	20

MOT #16 2023-11-27 16:40

MOT test number 459729430010

Result ✓ Passed

Next expiry date 2024-11-26

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Rear Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15 2023-11-27 11:52

MOT test number 882197111985

Result ✗ Failed

**Advice** Rear Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))

**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))

MOT #14 2022-08-16 15:48

MOT test number 430423423568

Result ✓ Passed

**MOT #13** 2022-08-12 10:28**MOT test number** 612486962578**Result** ✗ Failed**Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))**Fail** Offside Rear Service brake grabbing severely (1.2.1 (c))**Minor** Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))**Fail** Nearside Rear Service brake grabbing severely (1.2.1 (c))**MOT #12** 2021-01-20 08:49**MOT test number** 565485084751**Result** ✓ Passed**MOT #11** 2019-12-10 15:27**MOT test number** 130037180887**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-12-04 08:28**MOT test number** 796358632524**Result** ✓ Passed

**MOT #9** 2018-11-30 08:32**MOT test number** 398206530237**Result** ✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Minor** Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))
- Fail** Front Windscreen washer not working (3.5 (a))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 175/55/15 (5.2.3 (e))

**MOT #8** 2017-12-01 15:16**MOT test number** 490982107358**Result** ✓ Passed**MOT #7** 2017-11-29 08:38**MOT test number** 413519363560**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)

**MOT #6** 2016-12-01 14:46**MOT test number** 377366276821**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-12-01 11:01**MOT test number** 405113433767**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-12-02 10:06**MOT test number** 406568230853**Result** ✓ Passed**MOT #3** 2014-12-05 08:11**MOT test number** 396199534351**Result** ✓ Passed**Notice** Oil leak**MOT #2** 2014-01-06 16:11**MOT test number** 227946504081**Result** ✓ Passed



MOT #1	2013-12-30 12:31
MOT test number	105974263393
Result	✗ Failed
<div>Fail</div> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)	
<div>Advice</div> Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)	





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
26 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	26 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SMART had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SMART is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-12-23
Last registration	2023-11-27
Complete history	<a href="#">See info</a>



Registration #1	2010-12-23	16 mi
Registration #2	2013-12-30	12.196 mi
Registration #3	2014-01-06	12.197 mi
Registration #4	2014-12-05	23.755 mi
Registration #5	2015-12-02	18.711 mi
Registration #6	2016-12-01	22.875 mi
Registration #7	2016-12-01	22.875 mi
Registration #8	2017-11-29	25.538 mi
Registration #9	2017-12-01	25.540 mi
Registration #10	2018-11-30	28.971 mi
Registration #11	2018-12-04	28.971 mi
Registration #12	2019-12-31	32.377 mi
Registration #13	2020-12-31	35.783 mi
Registration #14	2021-12-31	39.189 mi
Registration #15	2022-12-31	42.595 mi
Registration #16	2023-11-27	46.001 mi
Registration #17	2023-11-27	46.001 mi
Registration #18	2023-11-27	46.001 mi
Registration #19	2023-11-27	46.001 mi
Registration #20	2023-11-27	46.001 mi
Registration #21	2023-11-27	46.001 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	99 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21CM3838