





report date: 2024-03-29

### General information

Make	JAGUAR
Model	X-TYPE V6 SE
Colour	Blue
Year of manufacture	2005
Top speed	127 mph
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	157 BHP
Max. torque	200 Nm at 4.100 rpm
Engine capacity	2.099 сс
Cylinders	6
Fuel type	Petrol
Consumption city	19.8 mpg
Consumption extra urban	38.2 mpg
Consumption combined	28.3 mpg
CO2 emission	239 g/km
CO2 label	L



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date 2021-12-25

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



B 4	$\sim$	- 1				
Μ	()	1	าเ	ST	'n	rv

MOT expiry date	2025-01-18
MOT pass rate	95 %
MOT passed	18
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #19		2024-01-11 11:42
MOT test	number	100706089494
Result		✓ Passed
Next expi	iry date	2025-01-18
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	) (ii))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (i))	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D	bushes (5.3.4 (a)
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #18	2023-01-09 16:34
MOT test number	702815765328
Result	✓ Passed

MOT #17	2022-01-19 13:38
MOT test number	134042505024
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



MOT #16 2021-08-12 10:56

**MOT test number** 299042741903

Result \rightarrow Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2021-02-15 12:46

MOT test number 345960926422

**Result** 
✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2020-08-18 12:31

**MOT test number** 177341207813

**Result** ✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2019-08-15 12:17

MOT test number 898025695437

**MOT #12** 2019-08-14 15:35

MOT test number 636400007420

Result X Failed

Fail Offside Front Headlamp aim not tested (4.1.2 (b))

**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/13



MOT #11

MOT test number

996976812580

Result

Advice (b))

Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4

Advice Offside Front Headlamp has a product on the (b))	e lens but not seriously reducing light output (4.1.4
MOT #10	2017-03-15 16:34
MOT test number	694543900725
Result	✓ Passed
MOT #9	2016-03-29 11:09
MOT test number	786460375420
Result	✓ Passed
MOT #8	2015-03-23 09:25
MOT test number	659832185025
Result	✓ Passed
MOT #7	2014-03-13 12:19
MOT test number	479822474063
Result	✓ Passed
MOT #6	2013-03-25 14:14
MOT test number	626754483052
Result	<b>✓</b> Passed
MOT #5	2012-03-15 13:34
MOT test number	478655272035

MOT #5	2012-03-15 13:34
MOT test number	478655272035
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



MOT #4	2011-03-07 10:25
MOT test number	255756161026
Result	✓ Passed
Notice Bothsides front tyres wearing on inner edges	

Notice Bothsides front tyres wearing on inner edges	
MOT #3	2010-03-09 11:22
MOT test number	851068560014
Result	<b>✓</b> Passed
MOT #2	2009-03-05 10:04
MOT test number	161234469011
Result	✓ Passed
MOT #1	2008-03-04 10:10
MOT test number	334734268035
Result	✓ Passed

CarCheck.co.uk page 6/13





### Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	18 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		AR
THE STATE OF THE S		
***************************************		
***************************************		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-30
Last registration	2024-01-11
Complete history	See info



Registration #1	2005-03-30	7 mi
Registration #2	2008-03-04	9.421 mi
Registration #3	2009-03-05	11.546 mi
Registration #4	2010-03-09	13.941 mi
Registration #5	2011-03-07	16.264 mi
Registration #6	2012-03-15	18.148 mi
Registration #7	2013-03-25	19.754 mi
Registration #8	2014-03-13	20.965 mi
Registration #9	2015-03-23	22.599 mi
Registration #10	2016-03-29	24.542 mi
Registration #11	2017-03-15	25.439 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 ms

More info >

CarCheck.co.uk page 12/13



### Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1485 kg
Max. allowed weight	1995 kg

### Additional information

Fuel tank capacity	61 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	444560425YB

CarCheck.co.uk page 13/13