





report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Blue
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	101 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 3

Date 2021-06-12

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-06-05
------	------------

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-05-22

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

N/I	α		TC:	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2025-03-02
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	14
Total items failed	6

MOT #16	2024-02-07 11:15
MOT test number	773244802157
Result	✓ Passed
Next expiry date	2025-03-02

MOT #15	2023-03-03 17:12
MOT test number	119519100735
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #14	2023-03-03 17:12	
MOT test number	741146208854	
Result	X Failed	
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))		

MOT #13	2022-03-01 11:51
MOT test number	600908083334
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #11

MOT test number

Result

Advice Oil leak, but not excessive under (8.4.1 (a) (i))

 MOT #10
 2019-07-20 08:35

 MOT test number
 707106886847

 Result
 ✓ Passed

MOT #9

MOT test number

123236420320

Result

✓ Passed

MOT test number

722884898462

Result

Advice Nearside Rear Rear position lamp(s) slightly discoloured (1.1.A.3e)

Advice Nearside Stop lamp slightly discoloured (1.2.1e)

Advice Offside Rear Rear position lamp(s) slightly discoloured (1.1.A.3e)

Advice Offside Stop lamp slightly discoloured (1.2.1e)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #72016-07-12 10:15MOT test number487159281760Result✓ PassedMOT #62016-07-12 10:15MOT test number585956217103ResultX FailedPass with rectificationOffside Front Headlamp aim too high (1.8)

MOT #5 2015-06-29 10:51 **MOT** test number 448370785118 Result Passed **Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a) Notice Front registration plate starting to delaminate Notice Engine covers fitted obscuring some components in the engine bay Advice Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a) Notice Rear registration plate slightly warped/deteriorated

MOT #4	2014-07-12 11:39
MOT test number	377023894157
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT test number

Result

Pass with rectification

Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Notice

Child seat fitted not allowing full inspection of adult belt

Pass with rectification

Offside Front Headlamp aim too low (1.8)

 MOT #2
 2013-07-24 08:10

 MOT test number
 318575803400

 Result
 ✓ Passed

MOT #1 2012-10-17 15:43

MOT test number 129841892297

Result ✓ Passed

CarCheck.co.uk page 6/13





report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	2 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this FORD had different number plates. ober of plates faste since

CarCheck.co.uk page 10/13



LR59XRX report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



LR59XRX report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-26
Last registration	2024-02-07
Complete history	See info



Registration #1	2009-11-26	27 mi
Registration #2	2012-10-17	23.169 mi
Registration #3	2013-07-24	26.464 mi
Registration #4	2014-07-12	36.188 mi
Registration #5	2015-06-29	45.355 mi
Registration #6	2016-07-12	57.643 mi
Registration #7	2016-07-12	57.643 mi
Registration #8	2017-07-18	63.499 mi
Registration #9	2018-07-16	63.857 mi
Registration #10	2019-07-20	68.585 mi
Registration #10 Registration #11	2019-07-20	68.585 mi
_	2019-07-20	68.585 mi
Registration #11	2019-07-20	68.585 mi
Registration #11 Registration #12	2019-07-20	68.585 mi
Registration #11 Registration #12 Registration #13	2019-07-20	68.585 mi
Registration #11 Registration #12 Registration #13 Registration #14	2019-07-20	68.585 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2019-07-20	68.585 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2019-07-20	68.585 mi

More info >

CarCheck.co.uk page 12/13



LR59XRX report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1501 mm
Length	4472 mm
Wheel base	2640 mm
Kerb weight	1340 kg
Max. allowed weight	1845 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 9K16398