



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T3
Colour	Grey
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-07-28
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-01
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	60
Total items failed	12

MOT #19	2023-07-20 09:22
MOT test number	737354728743
Result	✓ Passed
Next expiry date	2024-08-01

MOT #18	2022-07-30 18:36
MOT test number	378153186527
Result	✓ Passed
Advice	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #17	2022-07-30 15:07
MOT test number	517847205430
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #16**

2021-08-02 15:27

**MOT test number**

840253240055

**Result**

✓ Passed

- Advice** Offside Rear Parking (secondary brake) grabbing slightly - ( slight ) (1.3.1 (c))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened - ( slight ) (1.1.14 (a) (ii))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn bush worn - ( slight ) (5.1.2 (b) (i))

**MOT #15**

2021-07-31 18:32

**MOT test number**

240264621458

**Result**

✗ Failed

- Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn bush worn - ( slight ) (5.1.2 (b) (i))
- Advice** Offside Rear Parking (secondary brake) grabbing slightly - ( slight ) (1.3.1 (c))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened - ( slight ) (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #14**

2020-07-17 09:41

**MOT test number**

268710454236

**Result**

✓ Passed

- Advice** Corrosion to various part of body underneath vehicle
- Advice** Fuel straps corroded
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** All suspension components corroded
- Advice** Coil spring corroded both front and both rear (5.3.1 (b) (i))

**MOT #13**

2019-07-12 15:26

**MOT test number**

440577720280

**Result**

✓ Passed

- Advice** Corrosion to various parts underneath of vehicle
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front tyre worn outer edge
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Petrol tank straps corroded
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2019-07-12 08:55

**MOT test number**

732405625291

**Result****✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Corrosion to various parts underneath of vehicle
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front tyre worn outer edge
- Advice** Petrol tank straps corroded

**MOT #11**

2018-07-11 13:23

**MOT test number**

713114895962

**Result****✓ Passed**

- Advice** Surface rust underneath body of car
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2018-07-11 09:57

**MOT test number**

193298367080

**Result**

✗ Failed

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Surface rust underneath body of car**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #9**

2017-07-25 08:46

**MOT test number**

585379119419

**Result**

✓ Passed

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Rear Nail in tyre**MOT #8**

2016-07-25 11:52

**MOT test number**

251958514918

**Result**

✓ Passed

**Advice** Offside Front Tyre wearing inner edge**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7**

2015-04-20 09:55

**MOT test number**

649930415137

**Result**

✓ Passed

**MOT #6** 2013-09-16 11:44**MOT test number** 226009453221**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-09-16 09:38**MOT test number** 898299753260**Result** ✗ Failed**Advice** Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Brake pad(s) modified and seriously weakened (3.5.1n)**MOT #4** 2012-09-25 09:26**MOT test number** 986809262206**Result** ✓ Passed**MOT #3** 2011-09-06 11:21**MOT test number** 989759541269**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front discs worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Hand brake travel high**Notice** Coolant leak





MOT #2	2010-08-20 11:08
MOT test number	593812130264
Result	✓ Passed
Notice	Nail in offside rear tyre
Notice	Rear tyres chopping slightly on inner edges
Notice	Handbrake travel high

MOT #1	2010-08-20 11:08
MOT test number	184752030220
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Notice	Handbrake travel high
Notice	Nail in offside rear tyre
Pass with rectification	Offside Headlamp aim too low (1.8)
Notice	Rear tyres chopping slightly on inner edges



Tax & MOT check

X

Untaxed

Tax expired:  
24 April 2024

✓

MOT

Expires:  
1 August 2024

Tax status	Expired at 24 April 2024
Days left	4 days too late
MOT expiry date	1 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-08
Last registration	2023-07-20
Complete history	<a href="#">See info</a>



Registration #1	2007-09-08	11 mi
Registration #2	2010-08-20	25.013 mi
Registration #3	2011-09-06	31.878 mi
Registration #4	2012-09-25	39.758 mi
Registration #5	2013-09-16	45.708 mi
Registration #6	2013-09-16	45.708 mi
Registration #7	2015-04-20	59.567 mi
Registration #8	2016-07-25	77.399 mi
Registration #9	2017-07-25	98.483 mi
Registration #10	2018-07-11	116.271 mi
Registration #11	2019-05-20	131.277 mi
Registration #12	2019-05-20	131.277 mi
Registration #13	2019-05-20	131.277 mi
Registration #14	2019-05-20	131.277 mi
Registration #15	2019-05-20	131.277 mi
Registration #16	2019-05-20	131.277 mi
Registration #17	2019-05-20	131.277 mi
Registration #18	2019-05-20	131.277 mi
Registration #19	2019-05-20	131.277 mi
Registration #20	2019-05-20	131.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7



<b>Number of axles</b>	2
<b>Engine number</b>	2AD521824