



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	2002
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-25
MOT pass rate	55 %
MOT passed	12
Failed MOT tests	10
Total advice items	41
Total items failed	35

MOT #22	2024-04-26 15:30
MOT test number	229152495065
Result	✓ Passed
Next expiry date	2025-04-25

MOT #21	2024-04-25 14:17
MOT test number	885030911542
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #20	2023-04-19 11:43
MOT test number	722242196559
Result	✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Nail in tyre

**MOT #19**

2023-04-19 11:43

MOT test number

837132051712

Result

✗ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Nail in tyre**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Horn not working (7.7 (a))**MOT #18**

2023-04-05 08:59

MOT test number

255759425097

Result

✗ Failed

Fail Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #17**

2022-04-13 10:53

MOT test number

583020647948

Result

✓ Passed

MOT #16

2014-10-06 12:18

MOT test number

337289874432

Result

✓ Passed

**MOT #15** 2013-12-20 12:10**MOT test number** 757764453354**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2013-12-20 09:21**MOT test number** 176424353331**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front passenger door cannot be opened from inside the vehicle (6.2.B.1b)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #13** 2012-11-15 15:19**MOT test number** 998580822373**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #12** 2012-11-15 10:14**MOT test number** 446800922472**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Notice** Centre exhaust mounting broken**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #11** 2011-10-29 08:12**MOT test number** 215502301373**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine light on.**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #10**

2011-10-28 11:01

MOT test number

807401001359

Result**✗ Failed****Fail** Offside Stop lamp not working (1.2.1b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine light on.**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Centre Stop lamp not working (1.2.1b)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #9**

2010-11-19 16:39

MOT test number

892373220314

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Engine light on.

**MOT #8** 2010-11-19 11:13**MOT test number** 793623020381**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Notice** Engine light on.**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Rear registration plate delaminated (6.3.1d)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2009-08-24 09:00**MOT test number** 360036939238**Result** ✓ Passed**Notice** Engine light on.**MOT #6** 2009-08-24 09:00**MOT test number** 903156139232**Result** ✗ Failed**Notice** Engine light on.**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5**

2008-07-07 12:19

MOT test number

791419688108

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)
- Notice** Nail in rear tyre

MOT #4

2008-07-07 12:19

MOT test number

872669388140

Result

✗ Failed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Pass with rectification** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Pass with rectification** Nearside Front Direction indicator incorrect colour (1.4.A.2f)
- Notice** Nail in rear tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)
- Pass with rectification** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Pass with rectification** Offside Front Direction indicator incorrect colour (1.4.A.2f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

2007-05-15 15:10

MOT test number

280585337478

Result

✓ Passed



MOT #2	2006-05-04 16:42
MOT test number	674554426153
Result	✓ Passed
Notice	Engine management lighth stays on
Notice	Front registration plate in poor condition

MOT #1	2006-04-29 09:54
MOT test number	323439616104
Result	✗ Failed
Notice	Off side front tyre side wall in poor condition
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

X

Untaxed

Tax expired:
19 April 2024

✓

MOT

Expires:
25 April 2025

Tax status	Expired at 19 April 2024
Days left	11 days too late
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-03-15
Last registration	2024-04-26
Complete history	See info



Registration #1	2002-03-15	27 mi
Registration #2	2006-04-29	38.421 mi
Registration #3	2006-05-04	38.516 mi
Registration #4	2007-05-15	48.521 mi
Registration #5	2008-07-07	59.473 mi
Registration #6	2009-08-24	72.833 mi
Registration #7	2010-11-19	81.996 mi
Registration #8	2010-11-19	81.996 mi
Registration #9	2011-10-28	89.009 mi
Registration #10	2011-10-29	89.053 mi
Registration #11	2012-11-15	97.254 mi
Registration #12	2013-05-20	105.277 mi
Registration #13	2013-05-20	105.277 mi
Registration #14	2013-05-20	105.277 mi
Registration #15	2013-05-20	105.277 mi
Registration #16	2013-05-20	105.277 mi
Registration #17	2013-05-20	105.277 mi
Registration #18	2013-05-20	105.277 mi
Registration #19	2013-05-20	105.277 mi
Registration #20	2013-05-20	105.277 mi
Registration #21	2013-05-20	105.277 mi
Registration #22	2013-05-20	105.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1230 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2

Engine number

AZJ 702054