



TOYOTA



report date: 2024-03-29

General information

| | |
|---------------------|---------------------|
| Make | TOYOTA |
| Model | PREVIA D-4D T3 7STR |
| Colour | Silver |
| Year of manufacture | 2006 |
| Top speed | 109 mph |
| 0 - 60 mph | 13.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 114 BHP |
| Max. torque | 250 Nm at 3.000 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.4 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 39.2 mpg |
| CO2 emission | 191 g/km |
| CO2 label | J |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-17 |
| Pictures | 8 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-01 |
| MOT pass rate | 86 % |
| MOT passed | 18 |
| Failed MOT tests | 3 |
| Total advice items | 24 |
| Total items failed | 4 |

MOT #21 2023-11-20 11:01

MOT test number 529349824727

Result ✓ Passed

Next expiry date 2024-12-01

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both sides (5.1.2 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #20 2022-12-02 15:40

MOT test number 768784950664

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))

MOT #19 2021-11-29 16:43

MOT test number 609186416591

Result ✓ Passed

- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #18**

2020-10-20 09:57

MOT test number

633946157820

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17

2020-09-30 13:38

MOT test number

806492265864

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- DANGEROUS** Steering rack insecure to the extent there is excessive movement at the mountings (2.1.3 (a) (ii))

MOT #16

2019-09-25 11:36

MOT test number

507501067544

Result

✓ Passed

MOT #15

2018-10-04 15:11

MOT test number

371585652259

Result

✓ Passed

- Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front slight freeplay felt in left side of steering rack

**MOT #14** 2018-10-04 15:11**MOT test number** 496746433141**Result** ✗ Failed

Pass with rectification Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Nearside Front slight freeplay felt in left side of steering rack

Minor Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Pass with rectification Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #13 2017-10-18 15:24**MOT test number** 607879873986**Result** ✓ Passed**MOT #12** 2016-10-14 15:08**MOT test number** 915348202251**Result** ✓ Passed**MOT #11** 2015-10-19 07:28**MOT test number** 946053914757**Result** ✓ Passed

Advice Oil leak

MOT #10 2015-10-19 07:28**MOT test number** 455139972870**Result** ✗ Failed

Advice Oil leak

Pass with rectification Front Headlamp aim too low (1.8)

Pass with rectification Offside Rear Stop lamp not working (1.2.1b)

**MOT #9** 2014-09-29 16:11**MOT test number** 315072474209**Result** ✓ Passed**MOT #8** 2013-10-01 15:40**MOT test number** 536244373225**Result** ✓ Passed**MOT #7** 2012-10-08 15:54**MOT test number** 445132282265**Result** ✓ Passed**MOT #6** 2011-10-19 17:03**MOT test number** 547002991256**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2010-10-21 14:46**MOT test number** 633734290272**Result** ✓ Passed**MOT #4** 2009-09-28 09:49**MOT test number** 723071779245**Result** ✓ Passed**MOT #3** 2008-10-22 11:17**MOT test number** 324336298475**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



| | |
|-----------------|------------------|
| MOT #2 | 2008-05-29 10:34 |
| MOT test number | 611890358168 |
| Result | ✓ Passed |
| MOT #1 | 2007-10-24 16:23 |
| MOT test number | 832927097285 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 126 |
| MOT expiry date | 1 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | GV56JTZ |
| Plate since | 2019-03-29 |
| Current registration | GV56JTZ |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 23 |
| First mileage registration | 2006-10-27 |
| Last registration | 2023-11-20 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-10-27 | 10 mi |
| Registration #2 | 2007-10-24 | 33.566 mi |
| Registration #3 | 2008-05-29 | 39.156 mi |
| Registration #4 | 2008-10-22 | 45.031 mi |
| Registration #5 | 2009-09-28 | 48.400 mi |
| Registration #6 | 2010-10-21 | 53.496 mi |
| Registration #7 | 2011-10-19 | 58.611 mi |
| Registration #8 | 2012-10-08 | 64.223 mi |
| Registration #9 | 2013-10-01 | 70.983 mi |
| Registration #10 | 2014-09-29 | 77.621 mi |
| Registration #11 | 2015-10-19 | 82.577 mi |
| Registration #12 | 2015-10-19 | 82.577 mi |
| Registration #13 | 2016-10-19 | 82.577 mi |
| Registration #14 | 2017-10-19 | 82.577 mi |
| Registration #15 | 2018-10-19 | 82.577 mi |
| Registration #16 | 2019-10-19 | 82.577 mi |
| Registration #17 | 2020-10-19 | 82.577 mi |
| Registration #18 | 2021-10-19 | 82.577 mi |
| Registration #19 | 2022-10-19 | 82.577 mi |
| Registration #20 | 2023-10-19 | 82.577 mi |
| Registration #21 | 2024-10-19 | 82.577 mi |
| Registration #22 | 2025-10-19 | 82.577 mi |
| Registration #23 | 2026-10-19 | 82.577 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1800 mm |
| Height | 1845 mm |
| Length | 4750 mm |
| Wheel base | 2900 mm |
| Kerb weight | 1740 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 87 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

Engine number

1CD0544307