



General information

Make	MINI
Model	MINI (R60) COOPER D
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-09-30
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-03
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	16
Total items failed	7

MOT #14	2023-09-27 17:06
MOT test number	677841537680
Result	✓ Passed
Next expiry date	2024-10-03

MOT #13	2022-09-22 12:05
MOT test number	565233349741
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2021-10-04 15:10
MOT test number	208468177047
Result	✓ Passed

**MOT #11** 2021-09-30 16:04**MOT test number** 157633707553**Result** ✗ Failed

- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))
- Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front number plate damaged
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both sides (5.3.4 (b) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))

**MOT #10** 2021-01-21 13:43**MOT test number** 970392833909**Result** ✓ Passed**MOT #9** 2020-01-19 11:51**MOT test number** 335082998317**Result** ✓ Passed**MOT #8** 2020-01-19 11:51**MOT test number** 250054392099**Result** ✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #7** 2018-11-13 16:04**MOT test number** 788407295967**Result** ✓ Passed**MOT #6** 2017-11-01 11:31**MOT test number** 521150044583**Result** ✓ Passed**MOT #5** 2016-09-16 11:47**MOT test number** 852717472696**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**MOT #4** 2016-09-15 11:20**MOT test number** 492736958894**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**MOT #3** 2015-09-09 14:31**MOT test number** 617067385920**Result** ✓ Passed**Advice** Offside Front Upper Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Front Upper Shock absorber has a slightly worn bush (2.7.4)



MOT #2	2014-09-15 16:34
MOT test number	226318454283
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components

MOT #1	2014-06-13 09:03
MOT test number	656364164157
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
3 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	3 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-30
Last registration	2023-09-27
Complete history	<a href="#">See info</a>



Registration #1	2011-06-30	28 mi
Registration #2	2014-06-13	38.738 mi
Registration #3	2014-09-15	42.220 mi
Registration #4	2015-09-09	53.729 mi
Registration #5	2016-09-15	63.684 mi
Registration #6	2016-09-16	63.684 mi
Registration #7	2017-11-01	77.460 mi
Registration #8	2018-11-13	87.525 mi
Registration #9	2019-05-29	95.377 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	73137786