



Mercedes-Benz

 **BG57PHA**

report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-05
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-09
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	6
Total items failed	9

MOT #17	2023-07-10 10:13
MOT test number	910088664378
Result	✓ Passed
Next expiry date	2024-07-09

MOT #16	2023-06-29 15:42
MOT test number	280666266255
Result	✗ Failed
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Electronic stability control warning lamp indicates a fault (7.12 (e))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #15	2021-10-04 12:55
MOT test number	382867834179
Result	✓ Passed
Advice	Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

**MOT #14** 2021-10-04 12:55**MOT test number** 899782539884**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))**MOT #13** 2020-09-04 09:37**MOT test number** 481413955842**Result** ✓ Passed**MOT #12** 2020-09-04 09:37**MOT test number** 220869793886**Result** ✗ Failed**Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #11** 2019-04-01 16:46**MOT test number** 415659875370**Result** ✓ Passed**MOT #10** 2019-04-01 16:46**MOT test number** 602980043644**Result** ✗ Failed**Pass with rectification** Front Undertray insecure (8.1.1 (b) (i))**MOT #9** 2017-03-27 08:50**MOT test number** 960995265544**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2016-04-12 07:14**MOT test number** 375012209135**Result** ✓ Passed**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #7** 2013-12-28 12:12**MOT test number** 318612263376**Result** ✓ Passed**MOT #6** 2013-01-17 10:57**MOT test number** 279787513092**Result** ✓ Passed**Notice** Both rear tyres very close to legal limits**MOT #5** 2013-01-16 11:19**MOT test number** 948116313080**Result** ✗ Failed**Notice** Both rear tyres very close to legal limits**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2012-01-14 09:52**MOT test number** 229924612067**Result** ✓ Passed**MOT #3** 2011-01-17 15:28**MOT test number** 968977611051**Result** ✓ Passed



MOT #2	2010-10-16 11:21
MOT test number	282199480238
Result	✓ Passed

MOT #1	2010-10-16 09:48
MOT test number	584979780274
Result	✗ Failed

Fail

Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-10-12
Last registration	2023-07-10
Complete history	See info



Registration #1	2007-10-12	18 mi
Registration #2	2010-10-16	25.729 mi
Registration #3	2010-10-16	25.729 mi
Registration #4	2011-01-17	27.335 mi
Registration #5	2012-01-14	38.634 mi
Registration #6	2013-01-16	48.439 mi
Registration #7	2013-01-17	48.448 mi
Registration #8	2013-12-28	57.211 mi
Registration #9	2016-04-12	59.803 mi
Registration #10	2017-03-27	62.743 mi
Registration #11	2019-05-20	65.337 mi
Registration #12	2019-05-20	65.337 mi
Registration #13	2019-05-20	65.337 mi
Registration #14	2019-05-20	65.337 mi
Registration #15	2019-05-20	65.337 mi
Registration #16	2019-05-20	65.337 mi
Registration #17	2019-05-20	65.337 mi
Registration #18	2019-05-20	65.337 mi
Registration #19	2019-05-20	65.337 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430923168