





report date: 2024-03-28

# General information

Make	MERCEDES-BENZ
Model	CLA CLA 180 AMG LINE
Colour	White
Year of manufacture	2017
Top speed	130 mph
0 - 100 km/h	8.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	115 kW / 157 HP / 120 BHP
Max. torque	250 Nm at 1.250 rpm
Engine capacity	1.595 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

#### Entry 3

Date 2023-12-05

Pictures 0

Listing price <u>View report</u>

#### source: carcraft.co.uk

#### Entry 2

Date 2023-10-10

Pictures

Listing price <u>View report</u>










source: cargurus.co.uk

## Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-10-11
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #6	2023-10-12 09:12
MOT test number	213588017111
Result	<b>√</b> Passed
Next expiry date	2024-10-11

MOT #5	2022-09-29 11:55
MOT test number	192385297338
Result	✓ Passed

MOT #4		2022-09-28 15:19
MOT test	t number	600917127287
Result		<b>X</b> Failed
<b>Fail</b>	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))		5.2.3 (d) (ii))

MOT #3	2021-09-24 14:34
MOT test	<b>number</b> 518804065427
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin n/s and o/s (1.1.13 (a) (ii))
Advice	Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2021-09-24 08:13

**MOT test number** 430867366405

**Result** X Failed

Advice Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Rear Brake pad(s) wearing thin n/s and o/s (1.1.13 (a) (ii))

**Fail** Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #1** 2020-09-23 10:08

**MOT test number** 907694035098

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/11



KX67WNN
report date: 2024-03-28

Tax & MOT check





Tax status

Days left

MOT expiry date

Full MOT history

Valid until 1 December

217

217

See MOT history

# Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MERCEDES-BENZ had different number plates. mber of plates -More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

## Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-30
Last registration	2023-10-12
Complete history	See info



Registration #1	2017-09-30	7 mi
Registration #2	2020-09-23	36.290 mi
Registration #3		11.777 es
Registration #4	2021-09-24	43.459 mi
Registration #5	2021-09-24	43.459 mi
Registration #6		11.117 au
Registration #6 Registration #7		11.777 ea
		11.77 m
Registration #7		11.77 mi 11.77 mi 11.77 mi

More info >

CarCheck.co.uk page 10/11



KX67WNN
report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	2032 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1330 kg
Max. allowed weight	1920 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	4
CarChock co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	27091031314484