




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2015
Top speed	116 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	121 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-15
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	0

MOT #9	2023-09-29 13:50
MOT test number	585600727507
Result	✓ Passed
Next expiry date	2024-10-15

MOT #8	2023-09-29 09:46
MOT test number	336879864538
Result	✗ Failed
MAJOR Offside Front Side repeater not working (4.4.1 (a) (ii))	

MOT #7	2022-09-30 10:58
MOT test number	515965884654
Result	✓ Passed
Advice Offside Door mirror repeater dim. Lens damaged.	

**MOT #6** 2021-10-05 10:56**MOT test number** 248956100151**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Also inner edge bald! (5.2.3 (e))**Advice** Rear Coil spring corroded BOTH. (5.3.1 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush. (5.3.4 (a) (i))**Advice** Offside Rear Inner Nail in tyre Edge.**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Also inner edge bald! (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush. (5.3.4 (a) (i))**MOT #5** 2020-10-16 11:20**MOT test number** 395499985184**Result** ✓ Passed**MOT #4** 2020-10-15 15:45**MOT test number** 296349809338**Result** ✗ Failed**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #3** 2020-05-19 08:58**MOT test number** 879271173625**Result** ✓ Passed**MOT #2** 2019-04-18 12:23**MOT test number** 107557798902**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



MOT #1	2018-04-24 13:18
MOT test number	492295002287
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
15 October 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GL15GGX
Plate since	2019-06-29
Current registration	 GL15GGX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-04-22
Last registration	2023-09-29
Complete history	See info



Registration #1	2015-04-22	22 mi
Registration #2	2018-04-24	36.221 mi
Registration #3	2019-04-18	47.532 mi
Registration #4	2020-05-19	57.572 mi
Registration #5	2020-10-15	63.088 mi
Registration #6	2020-10-16	63.088 mi
Registration #7	2020-10-16	63.088 mi
Registration #8	2020-10-16	63.088 mi
Registration #9	2020-10-16	63.088 mi
Registration #10	2020-10-16	63.088 mi
Registration #11	2020-10-16	63.088 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1674 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1490 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	CAYCAY0859