





report date: 2024-03-28

General information

Make	MINI
Model	COOPER D
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



YF12XSP

report date: 2024-03-28

Internet history

Entry 5

Date 2022-11-14

Pictures 0

Listing price View report

source: carcraft.co.uk

Entry 4

Date 2022-09-23

Pictures 50

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 3

Date 2022-04-18

Pictures 17

Listing price <u>View report</u>









source: yesauto.com

Entry 2


Date	2022-03-01
Pictures	11

Listing price <u>View report</u>

CarCheck.co.uk page 2/12









source: cargurus.co.uk

Entry 1

Date 2021-01-29

Pictures 21

Listing price <u>View report</u>









source: yesauto.com



Pass with rectification

YF12XSP

report date: 2024-03-28

MOT history	
MOT expiry date	2024-11-09
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	5
Total items failed	4
MOT #15	2023-11-08 11:12
MOT test number	854881192679
Result	✓ Passed
Next expiry date	2024-11-09
MOT #14	2022-11-10 09:00
MOT test number	595198580507
Result	✓ Passed
MOT #13	2022-03-07 12:05
MOT test number	396573625916
Result	✓ Passed
MOT #12	2021-01-29 09:26
MOT test number	679599066085
Result	✓ Passed
MOT #11	2021-01-29 09:26
MOT test number	328096133441
Result	× Failed
	↑ Talled

CarCheck.co.uk page 3/12

Nearside Front Headlamp aim too low (4.1.2 (a))



YF12XSP

report date: 2024-03-28

MOT #10		2020-02-10 16:50
MOT test	number	705323068952
Result		✓ Passed
MOT #9		2020-01-24 14:32
MOT test	number	344116202456
Result		× Failed
MAJOR	Nearside Headlamp aim too high (4.1.2 (a))	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	

MOT #8	2019-02-27 16:55
MOT test number	776765034539
Result	✓ Passed
MOT #7	2019-01-22 09:40
MOT test number	907400049896
Result	✓ Passed
MOT #6	2018-06-19 08:39
MOT test number	816455449323
Result	✓ Passed
MOT #5	2017-08-07 16:58
MOT test number	364201376602
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #4 2017-08-07 16:58

MOT test number 744557783756

Result X Failed

Pass with rectification Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #3 2016-07-29 12:21

MOT test number 142967846557

MOT #2 2015-07-11 12:59

MOT test number 939072495143

MOT #1 2015-07-10 14:16

MOT test number 578621595110

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 5/12





Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.


Date	
Category	
Туре	

Damage 2
Date

Category

Туре

Damage 1



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e union mestery		
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>		

	More info >	
Plate changes See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2012-06-14
Last registration	2023-11-08
Complete history	See info



Registration #1	2012-06-14	29 mi
Registration #2	2015-07-10	26.012 mi
Registration #3	2015-07-11	26.015 mi
Registration #4	2016-07-29	39.720 mi
Registration #5	2017-08-07	52.232 mi
Registration #6	2017-08-07	52.232 mi
Registration #7	2018-06-19	59.301 mi
Registration #8	2019-01-22	64.038 mi
Registration #9	2019-02-27	64.215 mi
Registration #10	2020-01-24	69.324 mi
Registration #11	2020-02-10	69.343 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 au
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1335 kg
Max. allowed weight	1845 kg

Additional information

Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12

Number of axles 2

Engine number 70718349