



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Grey
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J



Internet history

Entry 1

Date	2021-08-24
Pictures	5
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-10-09
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #16 2023-10-09 10:58

MOT test number 362523890989

Result ✓ Passed

Next expiry date 2024-10-09

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #15 2022-10-10 10:00

MOT test number 566086163111

Result ✓ Passed

MOT #14 2021-09-27 17:02

MOT test number 328405803810

Result ✓ Passed

**MOT #13** 2021-09-07 14:23**MOT test number** 654877773031**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened pair (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #12** 2020-12-01 10:47**MOT test number** 696171115281**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both nearside and offside (1.1.14 (a) (ii))**MOT #11** 2019-12-05 11:04**MOT test number** 538490702167**Result** ✓ Passed**MOT #10** 2018-10-30 12:47**MOT test number** 545657228419**Result** ✓ Passed**MOT #9** 2018-01-17 15:18**MOT test number** 457810254941**Result** ✓ Passed**MOT #8** 2017-01-10 17:27**MOT test number** 607288438318**Result** ✓ Passed



MOT #7	2016-01-14 15:07
--------	------------------

MOT test number	549588938023
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #6	2015-01-28 11:15
--------	------------------

MOT test number	667128425010
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #5	2014-01-27 17:16
--------	------------------

MOT test number	109787024420
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #4	2013-01-28 10:28
--------	------------------

MOT test number	206278723085
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #3	2012-01-11 14:03
--------	------------------

MOT test number	179951712424
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2012-01-09 15:05
--------	------------------

MOT test number	255319202058
-----------------	--------------

Result	✗ Failed
--------	----------

Fail	Nearside Front Tyre(s) incorrect because a lightweight or space saving wheel is fitted (4.1.A.1b)
------	---

Pass with rectification	Nearside Front Track rod end loose (2.2.B.1d)
-------------------------	---

MOT #1	2011-01-20 16:50
--------	------------------

MOT test number	938240521011
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
9 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	9 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-01-30
Last registration	2023-10-09
Complete history	See info



Registration #1	2008-01-30	11 mi
Registration #2	2011-01-20	58.743 mi
Registration #3	2012-01-09	60.792 mi
Registration #4	2012-01-11	60.820 mi
Registration #5	2013-01-28	62.386 mi
Registration #6	2014-01-27	63.594 mi
Registration #7	2015-01-28	64.640 mi
Registration #8	2016-01-14	65.683 mi
Registration #9	2017-01-10	66.548 mi
Registration #10	2018-01-09	67.403 mi
Registration #11	2019-01-08	68.258 mi
Registration #12	2020-01-07	69.113 mi
Registration #13	2021-01-06	70.000 mi
Registration #14	2022-01-05	70.887 mi
Registration #15	2023-01-04	71.774 mi
Registration #16	2024-01-03	72.661 mi
Registration #17	2025-01-02	73.548 mi
Registration #18	2026-01-01	74.435 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	560100