



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Grey
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-07-05
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-24
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	24
Total items failed	9

MOT #12 2023-06-22 10:16

MOT test number 586469360689

Result ✓ Passed

Next expiry date 2024-06-24

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #11 2023-06-22 07:32

MOT test number 226516051822

Result ✗ Failed**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10 2022-06-20 15:54

MOT test number 109846746263

Result ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2021-06-23 13:44**MOT test number** 213332661162**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2021-06-23 09:44**MOT test number** 296697808687**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7** 2020-06-02 09:16**MOT test number** 364128246220**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2020-06-01 11:31**MOT test number** 496683006246**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 2054517 (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2019-06-15 12:08**MOT test number** 992153833339**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-06-15 08:25**MOT test number** 715461764407**Result** ✗ Failed**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #3** 2018-06-25 09:22**MOT test number** 553396311381**Result** ✓ Passed



MOT #2	2017-07-11 08:28
MOT test number	350656896633
Result	✓ Passed
Advice	Under-trays fitted obscuring some underside components

MOT #1	2017-07-11 08:28
MOT test number	962022912223
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
24 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	24 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-07-29
Last registration	2023-06-22
Complete history	See info



Registration #1	2014-07-29	24 mi
Registration #2	2017-07-11	24.737 mi
Registration #3	2017-07-11	24.737 mi
Registration #4	2018-06-25	33.262 mi
Registration #5	2019-06-15	47.764 mi
Registration #6	2019-06-15	47.764 mi
Registration #7	2020-06-01	60.874 mi
Registration #8	2020-06-01	60.874 mi
Registration #9	2020-06-01	60.874 mi
Registration #10	2020-06-01	60.874 mi
Registration #11	2020-06-01	60.874 mi
Registration #12	2020-06-01	60.874 mi
Registration #13	2020-06-01	60.874 mi
Registration #14	2020-06-01	60.874 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3167254