






report date: 2024-03-29

General information

| Make | HYUNDAI |
|---------------------|------------------|
| Model | IX35 CRDI SE NAV |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 112 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 1.800 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 40.9 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 51.4 mpg |
| CO2 emission | 145 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/11



Internet history

| Fn | trv | 1 |
|----|-------|---|
| | ILI Y | - |

| Life y 1 | |
|---------------|-------------|
| Date | 2021-12-27 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-07-01 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 1 |

| MOT #7 | | 2023-06-26 08:53 |
|---|---------|---------------------------|
| MOT test | number | 982030722591 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-07-01 |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing Cracking in tread area (5.2.3 (d) (ii)) | | |
| Advice Brake disc worn, pitted or scored, but not seriously weakened Both rear disc inner brake faces in poor condition (1.1.14 (a) (ii)) | | disc inner brake faces in |

| MOT #6 | 2022-06-17 18:11 |
|----------------------------|------------------|
| MOT test number | 396553740714 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2021-06-29 09:30 |
| MOT test number | 236391681151 |
| Result | ✓ Passed |
| Advice O/s/f fog lamp inop | |

| MOT #4 | 2021-06-29 09:30 |
|----------------------------|--|
| MOT test number | 117061224253 |
| Result | ★ Failed |
| Pass with rectification | Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii)) |
| Advice O/s/f fog lamp inop | |

CarCheck.co.uk page 3/11



MOT #3 2020-07-02 10:51

MOT test number 542995293015

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front fog lamp not working

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2019-04-16 11:28

MOT test number 630622465747

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1 2018-04-27 13:28

MOT test number 625552630893

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 63 |
| MOT expiry date | 1 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
|--|-------------|
| | |
| MARKET STATE OF THE STATE OF TH | |
| | |
| ************* | |
| | |
| THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR | |
| *************************************** | |
| ************ | |
| | |
| | More info > |
| | |
| Plate changes | |
| | |
| See in this check if this HYUNDAI had different number plates. | |
| | |
| Number of plates | , |
| | |
| Current registration | UK WEST |
| Plate since | |
| | |
| Current registration | UK UK |
| Finite since | |
| | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Combont info | |

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-04-15 |
| Last registration | 2023-06-26 |
| Complete history | See info |



| Registration #1 | 2015-04-15 | 20 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-04-27 | 26.392 mi |
| Registration #3 | 2019-04-16 | 34.811 mi |
| Registration #4 | 2020-07-02 | 42.697 mi |
| Registration #5 | 2021-06-29 | 50.555 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | D.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 88% |
| Pedestrian | 54% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



More info >

Dimensions & weight

| Width | 1820 mm |
|---------------------|---------|
| Height | 1665 mm |
| Length | 4410 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1679 kg |
| Max. allowed weight | 2140 kg |

Additional information

| Fuel tank capacity | 58 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/1 |

Number of axles 2

Engine number D4HAFZ093791