





General information

| Make | RENAULT |
|---------------------|----------------------------|
| Model | KADJAR DYNAMIQUE S NAV DCI |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 112 mph |
| 0 - 60 mph | 11.7 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 109 BHP |
|-------------------------|---------------------|
| Max. torque | 260 Nm at 1.750 rpm |
| Engine capacity | 1.461 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 70.6 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 72.4 mpg |
| CO2 emission | 103 g/km |
| CO2 label | В |







Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2021-02-04 |
| Pictures | 10 |
| Listing price | View report |









source: autoonline.co.uk

Entry 1

Date

Pictures

Listing price

35 View report

2021-01-28



source: yesauto.com









MOT history

| MOT expiry date | 2024-10-02 |
|--------------------|------------|
| MOT pass rate | 63 % |
| MOT passed | 5 |
| Failed MOT tests | 3 |
| Total advice items | 9 |
| Total items failed | 5 |

| MOT #8 | | 2023-10-03 11:43 |
|---------------------------|---|--------------------------|
| MOT test | number | 402596342117 |
| Result | | Passed |
| Next expi | ry date | 2024-10-02 |
| Advice (i)) | Offside Front Suspension arm pin or bush worn but not resulting in excess | sive movement (5.3.4 (a) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 2.1mm (5.2.3 (| e)) |
| Advice (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in exce | ssive movement (5.3.4 |
| Advice (5.2.3 (e)) | Offside Rear Tyre worn close to legal limit/worn on edge 2.4mm and badly | v distorted inner edge |

| MOT #7 | 2023-09-27 14:38 | |
|--|---------------------|--|
| MOT test number | 363436930496 | |
| Result | 🗙 Failed | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.1mm (5.2.3 (e)) | | |
| Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) | | |
| FailOffside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) | | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.4mm and badly distorted inner edge (5.2.3 (e)) | | |
| Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) | | |
| Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive m (i)) | novement (5.3.4 (a) | |





| МОТ #6 | 2022-08-30 16:27 |
|--|------------------|
| MOT test number | 670307992560 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2022-08-30 13:21 |
| MOT test number | 362431330980 |
| Result | 🗙 Failed |
| Fail Front Windscreen washer not working (3.5 (a)) | |
| MOT #4 | 2021-09-29 09:00 |
| MOT test number | 258148955263 |
| Result | Passed |
| | |
| МОТ #3 | 2020-09-28 13:29 |
| MOT test number | 426642870706 |
| Result | Passed |
| | |
| MOT #2 | 2020-09-25 11:22 |
| MOT test number | 237248769363 |
| Result | 🗙 Failed |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| | |
| MOT #1 | 2020-06-20 05:08 |
| MOT test number | 385148921674 |
| Result | ✓ Passed |
| | |

Advice COVID-19 6 MONTH EXTENSION



Tax & MOT check

| √ Taxed | √ МОТ |
|-------------------------------|-----------------------------------|
| Tax due: 1 May 2025 | Expires: 2 October 2024 |
| Tax status | Valid until 1 May |
| Days left | 368 |
| MOT expiry date | 2 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ********** | |
| ******** | |
| NUMBER OF CONTRACT OF CONTRACT. | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2017-06-28 |
| Last registration | 2023-10-03 |
| Complete history | See info |



| Registration #1 | 2017-06-28 | 12 mi |
|------------------|------------|------------|
| Registration #2 | 2020-09-25 | 14.451 mi |
| Registration #3 | 2020-09-28 | 14.451 mi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.317 mi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 81% |
| Pedestrian | 74% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1836 mm |
| Height | 1613 mm |
| Length | 4449 mm |
| Wheel base | 2646 mm |
| Kerb weight | 1421 kg |
| Max. allowed weight | 1951 kg |
| Additional information | |
| Fuel tank capacity | 55 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | D061905 |