



HYUNDAI



EFI4NZB


report date: 2024-03-29

General information

| | |
|---------------------|----------------------------|
| Make | HYUNDAI |
| Model | I30 CRDI ACTIVE BLUE DRIVE |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 108 BHP |
| Max. torque | 260 Nm at 2.750 rpm |
| Engine capacity | 1.582 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 68.9 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 76.3 mpg |
| CO2 emission | 97 g/km |
| CO2 label | A |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-08 |
| Pictures | 10 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-13 |
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 20 |
| Total items failed | 6 |

| | |
|------------------|------------------|
| MOT #11 | 2023-11-22 11:34 |
| MOT test number | 839847892529 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-13 |

| | |
|-----------------|---|
| MOT #10 | 2022-11-23 10:01 |
| MOT test number | 562135365619 |
| Result | ✓ Passed |
| Advice | Front Track rod end ball joint has slight play both front track end (2.1.3 (b) (i)) |

| | |
|-------------------------|---|
| MOT #9 | 2022-11-23 10:01 |
| MOT test number | 358270815560 |
| Result | ✗ Failed |
| Advice | Front Track rod end ball joint has slight play both front track end (2.1.3 (b) (i)) |
| Pass with rectification | Nearside Rear Position lamp not working (4.2.1 (a) (ii)) |

| | |
|-----------------|------------------|
| MOT #8 | 2021-11-18 10:11 |
| MOT test number | 816283804741 |
| Result | ✓ Passed |

**MOT #7** 2021-11-18 10:11**MOT test number** 221301432323**Result** ✗ Failed

Pass with rectification Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #6 2020-12-14 09:30**MOT test number** 853181310839**Result** ✓ Passed**MOT #5** 2019-06-10 09:13**MOT test number** 383121871127**Result** ✓ Passed**MOT #4** 2019-06-10 09:13**MOT test number** 950577116661**Result** ✗ Failed

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Pass with rectification Front Headlamp aim too high both (4.1.2 (a))



MOT #3

2018-06-05 14:48

MOT test number

995238236290

Result

✓ Passed

- Advice

Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
- Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
- Minor

Offside Windscreen wiper blade defective smearing (3.4 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
- Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
- Advice

Vehicles internal headlight adjuster altered to recheck lights



| | |
|-------------------------|--|
| MOT #2 | 2018-06-05 14:47 |
| MOT test number | 994658447123 |
| Result | ✗ Failed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e)) |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e)) |
| Advice | Vehicles internal headlight adjuster altered to recheck lights |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e)) |
| Advice | Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e)) |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Minor | Offside Windscreen wiper blade defective smearing (3.4 (b) (i)) |
| Pass with rectification | Front Registration plate insecure (0.1 (a)) |

| | |
|-----------------|------------------|
| MOT #1 | 2017-06-06 09:52 |
| MOT test number | 941443173897 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
13 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 32 |
| MOT expiry date | 13 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2014-06-13 |
| Last registration | 2023-11-22 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2014-06-13 | 17 mi |
| Registration #2 | 2017-06-06 | 35.300 mi |
| Registration #3 | 2018-06-05 | 46.580 mi |
| Registration #4 | 2018-06-05 | 46.580 mi |
| Registration #5 | 2019-06-10 | 65.071 mi |
| Registration #6 | 2019-06-10 | 65.071 mi |
| Registration #7 | 2020-12-14 | 90.768 mi |
| Registration #8 | 2021-06-06 | 111.277 mi |
| Registration #9 | 2021-06-06 | 111.277 mi |
| Registration #10 | 2021-06-06 | 111.277 mi |
| Registration #11 | 2021-06-06 | 111.277 mi |
| Registration #12 | 2021-06-06 | 111.277 mi |
| Registration #13 | 2023-11-22 | 111.277 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 90% |
| Pedestrian | 67% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1780 mm |
| Height | 1470 mm |
| Length | 4300 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1360 kg |
| Max. allowed weight | 1810 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 53 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

Engine number

D4FBEZ568579