





report date: 2024-03-28

General information

Make	FIAT
Model	QUBO MULTIJET MYLIFE DUALOGIC
Colour	Blue
Year of manufacture	2014
Top speed	96 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-11-06

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2025-03-20
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	13
Total items failed	1

MOT #10	2024-03-18 13:05
MOT test number	297271927253
Result	✓ Passed
Next expiry date	2025-03-20

MOT #9	2024-03-18 13:05
MOT test number	656659038592
Result	× Failed
Pass with rectification Rear Exhaust syst	rem insecure (6.1.2 (a))

MOT #8	2023-03-21 12:46
MOT test number	722269292063
Result	✓ Passed

Result	▼ rasseu	
MOT #7	2022-02-03 10:32	
MOT test	number 176868760023	
Result	✓ Passed	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on limit inner edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge on limit inner edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6

MOT test number

103434966028

Result

Advice Front tyres starting to wear inner edges

2021-01-28 10:58

103434966028

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge ON LEGAL LIMIT (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #4
 2019-01-31 15:52

 MOT test number
 525735031155

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Result

MAJOR Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2

MOT test number

220265793903

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1		2017-01-25 11:15
MOT test	number	728929799958
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)	
Advice	Nearside Rear tyre worn on outer edge	
Advice	Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)	

CarCheck.co.uk page 5/12



DU63LPO report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

THE PROPERTY OF THE PROPERTY O	
Plate changes	More info >
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-02-04
Last registration	2024-03-18
Complete history	See info



Registration #1	2014-02-04	9 mi
Registration #2	2017-01-25	11.367 mi
Registration #3	2018-01-24	17.531 mi
Registration #4	2019-01-31	23.626 mi
Registration #5	2019-01-31	23.626 mi
Registration #6	2020-01-20	29.082 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	5160351

CarCheck.co.uk page 12/12