



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVT-I XT3
Colour	Green
Year of manufacture	2004
Top speed	109 mph
0 - 60 mph	10.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	37.2 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-03
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-29
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	42
Total items failed	11

MOT #23 2023-09-25 14:01

MOT test number 626673238733

Result ✓ Passed

Next expiry date 2024-09-29

- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Underside heavily corroding suspension chassis etc
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake hose slightly deteriorated both sides (1.1.12 (b) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #22 2022-09-30 14:53

MOT test number 654309195208

Result ✓ Passed

- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Corrosion under car and on suspension parts
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #21**

2021-09-30 15:53

MOT test number

840905756042

Result

✓ Passed

- Advice** Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Brake disc worn, but not excessively 'Front + Rear' (1.1.14 (a) (i))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output 'Both' (4.1.4 (b))

MOT #20

2021-09-30 14:12

MOT test number

382140081364

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output 'Both' (4.1.4 (b))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Brake disc worn, but not excessively 'Front + Rear' (1.1.14 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #19**

2020-11-30 10:51

MOT test number

258862793255

Result

✓ Passed

- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #18

2020-11-26 10:37

MOT test number

760108844118

Result

✗ Failed

- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #17

2019-05-16 09:23

MOT test number

308934700121

Result

✓ Passed

**MOT #16** 2018-06-05 14:36**MOT test number** 797104482170**Result** ✓ Passed**MOT #15** 2018-05-31 10:12**MOT test number** 141629321740**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2017-06-06 10:26**MOT test number** 292928475325**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Towball/hitch not fitted at time of test**MOT #13** 2016-06-09 13:48**MOT test number** 807330832664**Result** ✓ Passed**Advice** Towball/hitch not fitted at time of test**Advice** Rear Brake pipe slightly corroded across the rear (3.6.B.2c)

**MOT #12** 2016-06-08 13:48**MOT test number** 847022993071**Result** ✗ Failed**Advice** Rear Brake pipe slightly corroded across the rear (3.6.B.2c)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Towball/hitch not fitted at time of test**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #11** 2015-06-12 16:54**MOT test number** 958703565187**Result** ✓ Passed**Notice** Tow ball/hitch not fitted at time of test**MOT #10** 2015-06-10 10:05**MOT test number** 228311265479**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Tow ball/hitch not fitted at time of test**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Notice** Items removed from driver's view prior to test**MOT #9** 2014-06-13 15:20**MOT test number** 409274764104**Result** ✓ Passed

**MOT #8** 2014-06-13 09:52**MOT test number** 258254864189**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #7** 2013-06-15 10:12**MOT test number** 355186263100**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2012-04-30 12:09**MOT test number** 225861222196**Result** ✓ Passed**MOT #5** 2011-05-20 10:13**MOT test number** 629010141107**Result** ✓ Passed**MOT #4** 2010-05-10 13:49**MOT test number** 411150330185**Result** ✓ Passed**MOT #3** 2009-05-18 10:07**MOT test number** 901008939100**Result** ✓ Passed**MOT #2** 2008-04-28 09:30**MOT test number** 521369818133**Result** ✓ Passed



MOT #1	2007-05-08 13:34
MOT test number	642778827113
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
29 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-05-27
Last registration	2023-09-25
Complete history	See info



Registration #1	2004-05-27	11 mi
Registration #2	2007-05-08	27.516 mi
Registration #3	2008-04-28	33.460 mi
Registration #4	2009-05-18	39.256 mi
Registration #5	2010-05-10	44.408 mi
Registration #6	2011-05-20	48.787 mi
Registration #7	2012-04-30	52.310 mi
Registration #8	2013-06-15	64.460 mi
Registration #9	2014-06-13	73.773 mi
Registration #10	2014-06-13	73.773 mi
Registration #11	2015-06-10	82.295 mi
Registration #12	2015-06-12	82.298 mi
Registration #13	2016-06-08	86.936 mi
Registration #14	2016-06-08	86.936 mi
Registration #15	2016-06-08	86.936 mi
Registration #16	2016-06-08	86.936 mi
Registration #17	2016-06-08	86.936 mi
Registration #18	2016-06-08	86.936 mi
Registration #19	2016-06-08	86.936 mi
Registration #20	2016-06-08	86.936 mi
Registration #21	2016-06-08	86.936 mi
Registration #22	2016-06-08	86.936 mi
Registration #23	2016-06-08	86.936 mi
Registration #24	2016-06-08	86.936 mi
Registration #25	2016-06-08	86.936 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1AZ1358652