





General information

| Make | JAGUAR |
|---------------------|----------------|
| Model | X-TYPE S |
| Colour | Green |
| Year of manufacture | 2006 |
| Top speed | 125 mph |
| 0 - 60 mph | 9.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 331 Nm at 1.800 rpm |
| Engine capacity | 1.988 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |







Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-08-26 |
| Pictures | 10 |
| Listing price | View report |









source: cargurus.co.uk



MOT history

| MOT expiry date | 2022-12-30 |
|--------------------|------------|
| MOT pass rate | 78 % |
| MOT passed | 14 |
| Failed MOT tests | 4 |
| Total advice items | 28 |
| Total items failed | 8 |

| MOT #18 | | 2023-06-21 15:17 |
|-------------------------|---|--------------------|
| MOT test | number | 678842006218 |
| Result | | 🗙 Failed |
| Minor | Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) | (i)) |
| MAJOR (5.3.4 (b) | Offside Front Outer Anti-roll bar ball joint dust cover no longer prevents the ingre (ii)) | ess of dirt lower |
| Advice | Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 | 3 (b) (i)) |
| Advice | Offside sill corroded | |
| MAJOR | Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) | |
| MAJOR | Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d)) | |
| Minor | Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (| b) (i)) |
| MAJOR (5.3.4 (b) | Nearside Front Outer Anti-roll bar ball joint dust cover no longer prevents the ing (ii)) | ress of dirt lower |
| Advice | Nearside sill corroded | |
| Advice | Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 | (b) (i)) |
| MAJOR | Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d)) | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |





| MOT #17 | 2021-12-15 13:53 |
|---|------------------------------|
| MOT test number | 900167340756 |
| Result | ✓ Passed |
| AdviceRear Coil spring corroded (5.3.1 (b) (i))MinorNearside Front Lower Suspension arm ball joint dust cover severely of | deteriorated (5.3.4 (b) (i)) |

| MOT #16 | 2020-12-11 13:15 |
|-----------------|------------------|
| MOT test number | 420429469585 |
| Result | ✓ Passed |

| MOT #15 | | 2019-12-18 09:00 |
|----------|--|------------------|
| MOT test | number | 287152371433 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #14 | 2018-12-20 08:50 |
|-----------------|------------------|
| MOT test number | 662550287959 |
| Result | ✓ Passed |
| | |
| MOT #12 | |

| MOI #13 | 2017-12-19 09:25 |
|-----------------|------------------|
| MOT test number | 683752591633 |
| Result | ✓ Passed |
| | |

| MOT #12 | 2016-12-15 09:11 |
|-----------------|------------------|
| MOT test number | 855555803499 |
| Result | ✓ Passed |



| MOT #11 | 2015-12-15 10:17 |
|--|------------------|
| MOT test number | 904233390775 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |
| | |
| MOT #10 | 2014-12-31 11:43 |
| MOT test number | 737845464338 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2014-12-29 12:52 |
| MOT test number | 917523564376 |
| Result | 🗙 Failed |
| Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) | |
| | |
| MOT #8 | 2013-12-06 10:51 |
| MOT test number | 226860343365 |
| Result | ✓ Passed |

Advice Nearside front brake fluctuating, but not excessively (3.7.B.3)

Offside front brake fluctuating, but not excessively (3.7.B.3)

Advice





HY06XGA report date: 2024-03-29

| MOT #7 | | 2013-12-06 10:51 |
|--|--|------------------|
| MOT test number | | 979960143310 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Headlamp aim too low (1.8) | |
| Pass with rectification | Offside Front Wheel nut(s) missing (4.2.A.1e) | |
| Pass with rectification | Offside Rear Wheel nut(s) missing (4.2.A.1e) | |
| Advice Nearside front brake fluctuating, but not excessively (3.7.B.3) | | |
| Pass with rectification | Offside Headlamp aim too low (1.8) | |
| Pass with rectification | Nearside Front Wheel nut(s) missing (4.2.A.1e) | |
| Advice Offside front bra | ke fluctuating, but not excessively (3.7.B.3) | |

| MOT #6 | 2013-01-15 10:40 |
|-----------------|------------------|
| MOT test number | 909905513056 |
| Result | ✓ Passed |

| MOT #5 | 2012-01-18 09:58 |
|-------------------------|--|
| MOT test | number 477328512027 |
| Result | ✓ Passed |
| Advice (2.4.G.2) | Nearside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement |
| Advice | Parking brake lever has little reserve travel (3.1.6b) |
| Advice (2.4.G.2) | Offside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement |

| МОТ #4 | 2011-01-19 17:34 |
|-----------------|------------------|
| MOT test number | 938049411032 |
| Result | ✓ Passed |





| МОТ #3 | 2010-03-22 10:39 |
|---|----------------------|
| MOT test number | 380391880017 |
| Result | ✓ Passed |
| Notice Handbrake lever has high travel | |
| MOT #2 | 2010-03-22 10:39 |
| MOT test number | 361521880028 |
| Result | 🗙 Failed |
| Notice Handbrake lever has high travel | |
| Pass with rectificationNearside Front Windscreen wiper does not clear the wip | ndscreen effectively |
| Pass with rectification Front registration plate deteriorated (6.3.1d) | |

| MOT #1 | 2009-03-04 17:02 |
|---|------------------|
| MOT test number | 693513969045 |
| Result | ✓ Passed |
| Advice Nearside Rear Rear wheel bearing has slight play (2.6.2) | |



HY06XGA report date: 2024-03-29

Tax & MOT check

| X Untaxed Tax expired: 26 June 2023 | X MOT Expired: 30 December 2022 |
|--|--|
| Tax status | Expired at 26 June 2023 |
| Days left | 309 days too late |
| MOT expiry date | 30 December 2022 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| | E Store |
| Date | 1. E |
| Category | amt |
| Туре | |

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| *********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this JAGUAR had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| | |
| Plate since | |





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2006-03-24 |
| Last registration | 2023-06-21 |
| Complete history | See info |



| Registration #1 | 2006-03-24 | 22 mi |
|------------------|------------|------------|
| Registration #2 | 2009-03-04 | 16.683 mi |
| Registration #3 | 2010-03-22 | 21.786 mi |
| Registration #4 | 2011-01-19 | 26.176 mi |
| Registration #5 | 2012-01-18 | 29.314 mi |
| Registration #6 | 2013-01-15 | 32.007 mi |
| Registration #7 | 2013-12-06 | 38.397 mi |
| Registration #8 | 2014-12-29 | 47.617 mi |
| Registration #9 | 2014-12-31 | 47.617 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 esi |
| Registration #17 | | 11.777 mi |
| Registration #18 | | 11.117 esi |





Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|--|--------------------------|
| Width | 2003 mm |
| Height | 1392 mm |
| Length | 4672 mm |
| Wheel base | 2710 mm |
| Kerb weight | 1502 kg |
| Max. allowed weight | 2015 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 61 l |
| | 61 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 4 |