





report date: 2024-03-28

### General information

| Make                | FIAT            |
|---------------------|-----------------|
| Model               | DOBLO 8V ACTIVE |
| Colour              | Silver          |
| Year of manufacture | 2007            |
| Top speed           | 92 mph          |
| 0 - 60 mph          | 17.0 seconds    |
| Gearbox             | 5 speed Manual  |

### Engine & fuel consumption

| Power                   | 77 BHP              |
|-------------------------|---------------------|
| Max. torque             | 115 Nm at 3.000 rpm |
| Engine capacity         | 1.368 сс            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 30.7 mpg            |
| Consumption extra urban | 44.8 mpg            |
| Consumption combined    | 38.2 mpg            |
| CO2 emission            | 174 g/km            |
| CO2 label               | Н                   |



CarCheck.co.uk page 1/13



Internet history

#### Entry 1

| Date          | 2021-01-29         |  |
|---------------|--------------------|--|
| Pictures      | 1                  |  |
| Listing price | <u>View report</u> |  |



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date    | 2024-08-25 |
|--------------------|------------|
| MOT pass rate      | 81 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 3          |
| Total advice items | 10         |
| Total items failed | 6          |

| MOT #16   | 2023-08-23 10:30 |
|---|------------------|
| MOT test number   | 277803985269     |
| Result  | <b>✓</b> Passed  |
| Next expiry date 2024-08-25   |                  |
| Minor  (a) (i))  Offside Front Lower Windscreen damaged but not adversely affecting driver's view Stone chip. (3.2) |                  |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |

| MOT #15   | 2023-08-22 10:32 |  |
|---|------------------|--|
| MOT test number   | 197589363089     |  |
| Result  | <b>X</b> Failed  |  |
| Fail Offside Rear Rear reflector missing (4.8.2 (a) (ii))  Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's view Stone chip. (3.2 (a) (i)) |                  |  |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |  |

| MOT #14  |  | 2022-08-26 07:37 |
|----------|--|------------------|
| MOT test | number   | 462671898625     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing 185,65R15 (5.2.3 (d | ) (ii))          |

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2021-01-14 14:07

**MOT test number** 803107410396

MOT #12 2021-01-12 14:34

**MOT test number** 141025976241

Result × Failed

Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #11 2020-03-20 13:04

**MOT test number** 502011934807

Result \rightarrow Passed

**MOT #10** 2019-02-04 14:07

**MOT test number** 212914824973

Result \( \sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2017-09-14 14:31

MOT test number 442839547376

**Result** ✓ Passed

MOT #8 2016-09-15 13:25

**MOT test number** 125060120113

**Result** 
✓ Passed

CarCheck.co.uk page 4/13



MOT #7 2015-08-21 11:45

**MOT test number** 739023635293

**Result** ✓ Passed

**Notice** Nail in nearside rear tyre

**Notice** Advise: rear tyres perishing.

MOT #6 2014-09-09 09:04

**MOT test number** 498022054204

**Result** ✓ Passed

MOT #5 2013-09-18 10:52

**MOT test number** 435791863271

MOT #4 2012-10-24 14:27

**MOT test number** 698188792237

**Result** ✓ Passed

MOT #3 2011-11-24 14:16

**MOT test number** 668988021330

**MOT #2** 2010-11-25 11:04

**MOT test number** 590319920347

Result 

Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

513419620326

Result

Pass with rectification

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification

Offside Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 6/13



### Tax & MOT check



| Tax status       | Valid until 1 August |
|------------------|----------------------|
| Days left        | 95                   |
| MOT expiry date  | 25 August 2024       |
| Full MOT history | See MOT history      |

#### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | Н          |
| Single payment (12 months)              | £ 290,00,- |
| Single six month payment                | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| · ·   |           |    |
|---|-----------|----|
| For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I |           | e? |
|   |           |    |
|   |           |    |
|   |           |    |
|   |           |    |
| ********  |           |    |
|   |           |    |
| ***************************************   |           |    |
|   | More info | >  |
| Plate changes  See in this check if this FIAT had different number plates.  |           |    |
|   |           |    |
| Number of plates  |           | ,  |
| Current registration  | UK UK     |    |
| Plate since   |           |    |
| Current registration  | UK NE     |    |
| Plate since   |           |    |
|   | More info | >  |
|   |           |    |

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Control info      |  |

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 17         |
| First mileage registration | 2007-12-17 |
| Last registration          | 2023-08-23 |
| Complete history           | See info   |



| Registration #1  | 2007-12-17 | 16 mi     |
|------------------|------------|-----------|
| Registration #2  | 2010-11-25 | 7.733 mi  |
| Registration #3  | 2011-11-24 | 10.047 mi |
| Registration #4  | 2012-10-24 | 12.530 mi |
| Registration #5  | 2013-09-18 | 13.396 mi |
| Registration #6  | 2014-09-09 | 17.694 mi |
| Registration #7  | 2015-08-21 | 20.420 mi |
| Registration #8  | 2016-09-15 | 20.643 mi |
| Registration #9  | 2017-09-14 | 20.916 mi |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.177 mi |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 11.177 mi |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | D.777-ec  |
|                  |            |           |
| Registration #16 |            | 11.777 46 |

More info >

CarCheck.co.uk page 12/13



Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 |                 |
| 50482 |                 |
| 50501 |                 |
| 50566 |                 |
| 60567 |                 |
| 50569 |                 |

## Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



## Dimensions & weight

| Width      | 1722 mm |
|------------|---------|
| Height     | 1818 mm |
| Length     | 4253 mm |
| Wheel base | 2583 mm |

# Additional information

| Fuel tank capacity | 60 I                  |
|--------------------|-----------------------|
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of axles    | 2                     |
| Engine number      | 3908276               |

CarCheck.co.uk page 13/13