



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF GT TDI DSG
Colour	Black
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	142 g/km
CO2 label	F





MOT history

MOT expiry date	2024-11-03
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	31
Total items failed	21

MOT #15	2023-10-31 10:31
MOT test number	118738873684
Result	✓ Passed
Next expiry date	2024-11-03
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2022-11-04 09:56
MOT test number	399562760841
Result	✓ Passed

MOT #13	2021-11-01 14:55
MOT test number	710363699996
Result	✓ Passed
Minor	Central Front Windscreen damaged but not adversely affecting driver's view bottom (3.2 (a) (i))

**MOT #12**

2021-10-27 07:32

MOT test number

688857344427

Result**✗ Failed**

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn back bush (5.3.4 (a) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Central Front Windscreen damaged but not adversely affecting driver's view bottom (3.2 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Tyre fouling a part of the vehicle (5.2.3 (f))
- Fail** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Fail** Front Brake disc in such a condition that it is seriously weakened inside (1.1.14 (a) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn back bush (5.3.4 (a) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Tyre fouling a part of the vehicle (5.2.3 (f))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))



MOT #11

2020-10-30 18:16

MOT test number

646628580782

Result

✓ Passed

- Advice

Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Minor

Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #10** 2020-10-30 13:30**MOT test number** 689217627736**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2019-10-30 17:03**MOT test number** 811321235741**Result** ✓ Passed**MOT #8** 2018-10-01 15:26**MOT test number** 481709988330**Result** ✓ Passed**Advice** Tyres close to legal limit x4**Advice** Offside Rear anti roll link play**Advice** Windscreen cracked

**MOT #7** 2017-04-11 08:41**MOT test number** 923146043640**Result** ✓ Passed**Advice** O/s/f seatbelt webbing heavily frayed**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #6** 2016-04-19 09:48**MOT test number** 853688521680**Result** ✓ Passed**Advice** Undertrays fitted**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Both front tyres worn on inner edges**Advice** O/s/r tyre worn inner edge and has some perishing**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #5** 2015-04-20 14:19**MOT test number** 506670415165**Result** ✓ Passed**MOT #4** 2014-04-22 12:17**MOT test number** 178692714171**Result** ✓ Passed



MOT #3	2014-04-17 15:57
MOT test number	297637704494
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	Nearside front tyre tread worn of inner edge

MOT #2	2013-04-21 09:11
MOT test number	655791313187
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2012-09-03 15:17
MOT test number	766927142204
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
3 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	FE59WUO
Plate since	2019-06-29
Current registration	FE59WUO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-30
Last registration	2023-10-31
Complete history	See info



Registration #1	2009-09-30	19 mi
Registration #2	2012-09-03	64.312 mi
Registration #3	2013-04-21	74.986 mi
Registration #4	2014-04-17	97.423 mi
Registration #5	2014-04-22	97.563 mi
Registration #6	2015-04-20	122.300 mi
Registration #7	2016-04-19	145.212 mi
Registration #8	2017-04-11	168.828 mi
Registration #9	2018-04-11	192.444 mi
Registration #10	2019-04-11	216.060 mi
Registration #11	2020-04-11	239.676 mi
Registration #12	2021-04-11	263.292 mi
Registration #13	2022-04-11	286.908 mi
Registration #14	2023-04-11	310.524 mi
Registration #15	2023-10-31	334.140 mi
Registration #16	2024-03-28	357.756 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1322 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 657988