



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO VALVEMATIC ACTIVE
Colour	White
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	132 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-12-03
Pictures	14
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)

Entry 1

Date	2021-11-06
Pictures	15
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-02-11
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	21
Total items failed	7

MOT #11	2024-02-12 14:21
MOT test number	675599250633
Result	✓ Passed
Next expiry date	2025-02-11

MOT #10	2022-11-08 15:10
MOT test number	887342353775
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Exhaust mounting defective On centre section (6.1.2 (a))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement  
Wishbone bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement  
Wishbone bush (5.3.4 (a) (i))



<b>MOT #9</b>	2021-09-21 09:11
<b>MOT test number</b>	130448854867
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #8</b>	2020-09-25 16:06
<b>MOT test number</b>	357303567690
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

<b>MOT #7</b>	2020-09-23 14:12
<b>MOT test number</b>	555649160829
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Fail</b>	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Nearside Rear Brake pipe excessively corroded on axel (1.1.11 (c))
<b>Fail</b>	Offside Front Brake pipe excessively corroded (1.1.11 (c))
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Fail</b>	Offside Front Windscreen wiper does not clear the windscreen effectively Split (3.4 (b) (ii))
<b>Fail</b>	Offside Rear Brake pipe excessively corroded on axel (1.1.11 (c))

**MOT #6** 2019-10-04 13:21**MOT test number** 434745086917**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively discs lipped (1.1.14 (a) (i))**Advice** Rear Brake disc worn, but not excessively discs lipped (1.1.14 (a) (i))**MOT #5** 2018-09-27 11:11**MOT test number** 197056259651**Result** ✓ Passed**Advice** Front brake discs lipped**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2018-09-27 08:52**MOT test number** 955391475974**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front brake discs lipped**MOT #3** 2017-09-29 08:07**MOT test number** 727457916833**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2016-09-22 07:01**MOT test number** 568768607245**Result** ✓ Passed



MOT #1	2016-03-16 12:52
MOT test number	874070130345
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
11 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	11 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-04-05
Last registration	2024-02-12
Complete history	<a href="#">See info</a>



Registration #1	2013-04-05	12 mi
Registration #2	2016-03-16	20.230 mi
Registration #3	2016-09-22	22.825 mi
Registration #4	2017-09-29	38.491 mi
Registration #5	2018-09-27	58.720 mi
Registration #6	2018-09-27	58.720 mi
Registration #7	2019-10-04	74.242 mi
Registration #8	2019-10-04	74.242 mi
Registration #9	2019-10-04	74.242 mi
Registration #10	2019-10-04	74.242 mi
Registration #11	2019-10-04	74.242 mi
Registration #12	2019-10-04	74.242 mi
Registration #13	2019-10-04	74.242 mi
Registration #14	2019-10-04	74.242 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number	1ZRU592292
---------------	------------