



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	TUCSON N LINE T-GDI 2WD T-GDI N LINE
Colour	White
Year of manufacture	2020
Top speed	126 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	175 BHP
Max. torque	265 Nm at 4.500 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 4

Date	2023-10-04
Pictures	1
Listing price	<a href="#">View report</a>

□

source: [autoonline.co.uk](#)

Entry 3

Date	2023-09-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 2

Date	2021-11-25
Pictures	2
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-11-25
Pictures	0
Listing price	<a href="#">View report</a>

source: [heycar.co.uk](#)



## MOT history

MOT expiry date	2024-10-04
MOT pass rate	50 %
MOT passed	2
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #4	2023-10-05 16:10
MOT test number	596074803682
Result	✓ Passed
Next expiry date	2024-10-04

MOT #3	2023-10-02 16:24
MOT test number	989290404139
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2023-03-15 10:34
MOT test number	423984044367
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Inside edge. (5.2.3 (e))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Inside edge. (5.2.3 (e))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #12023-03-15 10:34

MOT test number300378508671

Result		✗ Failed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Inside edge. (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Inside edge. (5.2.3 (e))	
Pass with rectification	Offside Front Road wheel fixing missing (5.2.1 (a) (i))	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
4 October 2024

Tax status		Valid until 1 October
Days left		156
MOT expiry date		4 October 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2020-03-24
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2020-03-24	24 mi
Registration #2	2020-03-24	25.277 mi
Registration #3	2020-03-24	25.277 mi
Registration #4	2023-03-15	31.039 mi
Registration #5	2023-03-15	31.039 mi
Registration #6	2020-03-24	25.277 mi
Registration #7	2020-03-24	25.277 mi
Registration #8	2020-03-24	25.277 mi
Registration #9	2020-03-24	25.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1850 mm
Height	1650 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1545 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	62 l
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

G4FJKZ998877