



report date: 2024-03-28

General information

Make	MINI
Model	COOPER S
Colour	Grey
Year of manufacture	2015
Top speed	146 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	192 BHP
Max. torque	280 Nm at 4.600 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	136 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-04
Pictures	19
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-06-07
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	9
Total items failed	7

MOT #11	2023-06-07 09:52
MOT test number	465008561447
Result	✓ Passed
Next expiry date	2024-06-07

MOT #10	2023-06-07 09:11
MOT test number	445512596764
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9	2022-05-17 09:37
MOT test number	958311256055
Result	✓ Passed
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2021-06-08 15:43
MOT test number	244446170846
Result	✓ Passed

**MOT #7** 2021-03-15 16:06**MOT test number** 353567797828**Result** ✓ Passed**MOT #6** 2021-03-15 14:12**MOT test number** 812228737325**Result** ✓ Passed**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #5** 2020-06-23 13:15**MOT test number** 138739256741**Result** ✓ Passed**MOT #4** 2019-10-29 11:55**MOT test number** 980498761073**Result** ✓ Passed**MOT #3** 2019-10-28 11:13**MOT test number** 676077476637**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))



MOT #2	2018-10-10 08:43
MOT test number	993458530756
Result	✓ Passed
Advice	Both rear tyres feathered

MOT #1	2018-10-09 08:04
MOT test number	188736862171
Result	✗ Failed
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Both rear tyres feathered
Fail	Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
7 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YK65BEO
Plate since	2019-09-28
Current registration	YK65BEO
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-10-27
Last registration	2023-06-07
Complete history	See info



Registration #1	2015-10-27	7 mi
Registration #2	2018-10-09	21.156 mi
Registration #3	2018-10-10	21.156 mi
Registration #4	2019-10-28	32.269 mi
Registration #5	2019-10-29	32.269 mi
Registration #6	2020-06-23	33.959 mi
Registration #7	2021-03-15	41.101 mi
Registration #8	2022-06-07	55.277 mi
Registration #9	2022-06-07	55.277 mi
Registration #10	2022-06-07	55.277 mi
Registration #11	2022-06-07	55.277 mi
Registration #12	2022-06-07	55.277 mi
Registration #13	2022-06-07	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1414 mm
Length	3850 mm
Wheel base	2495 mm
Kerb weight	1235 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number

F2881208