



HYUNDAI

EJILKP


report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 COMFORT
Colour	Silver
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	142 g/km
CO2 label	F





## MOT history

MOT expiry date	2024-08-07
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	34
Total items failed	8

MOT #15	2023-08-08 15:36
MOT test number	587264361420
Result	✓ Passed
Next expiry date	2024-08-07
Advice	Fuel Pipe/s corroded

MOT #14	2023-08-07 17:12
MOT test number	391940953672
Result	✗ Failed
Advice	Fuel Pipe/s corroded
MAJOR	Offside Front Driver's door cannot be opened from inside the vehicle (6.2.3 (a))
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #13	2022-06-08 12:41
MOT test number	832259545726
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge perishing. (5.2.3 (e))

**MOT #12**

2022-05-04 12:46

**MOT test number**

164922460987

**Result****✗ Failed**

- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Driver's door cannot be opened from inside the vehicle (6.2.3 (a))
- MAJOR** Nearside Side repeater incorrect colour (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge + perishing (5.2.3 (e))
- Advice** Direction indicator slightly discoloured all (4.4.3 (a))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn inner front bush (5.3.4 (a) (i))

**MOT #11**

2021-05-05 15:08

**MOT test number**

658562439233

**Result****✓ Passed****MOT #10**

2020-04-02 10:05

**MOT test number**

654893624485

**Result****✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

**MOT #9**

2019-04-17 08:46

**MOT test number**

600399550469

**Result****✓ Passed**

**MOT #8** 2019-04-17 08:46**MOT test number** 288461121056**Result** ✗ Failed**Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #7** 2018-05-29 14:36**MOT test number** 714612108455**Result** ✓ Passed**Advice** Rear tyres perishing**MOT #6** 2017-06-02 13:57**MOT test number** 160233790836**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear tyres perishing**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2017-06-02 09:47**MOT test number** 728690825883**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear tyres perishing**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2016-06-07 13:54**MOT test number** 827667193256**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front tyre worn inner edge**Advice** Nearside Front tyre worn inner edge**MOT #3** 2016-06-07 09:59**MOT test number** 857443186594**Result** ✗ Failed**Fail** Offside Front Valve stem seriously damaged (4.1.D.1e)**Advice** Nearside Front tyre worn inner edge**Advice** Nearside Front wiper blade starting to split**Fail** Nearside Front Valve stem seriously damaged (4.1.D.1e)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Front tyre worn inner edge**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2015-04-27 09:13**MOT test number** 737687115139**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-04-07 10:00**MOT test number** 278927394085**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
7 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	7 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EJ11LKP
Plate since	2019-09-29
Current registration	EJ11LKP
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-30
Last registration	2023-08-08
Complete history	<a href="#">See info</a>



Registration #1	2011-04-30	29 mi
Registration #2	2014-04-07	36.178 mi
Registration #3	2015-04-27	48.823 mi
Registration #4	2016-06-07	58.588 mi
Registration #5	2016-06-07	58.588 mi
Registration #6	2017-06-02	63.619 mi
Registration #7	2017-06-02	63.619 mi
Registration #8	2018-05-29	67.343 mi
Registration #9	2019-05-29	71.377 mi
Registration #10	2019-05-29	71.377 mi
Registration #11	2019-05-29	71.377 mi
Registration #12	2019-05-29	71.377 mi
Registration #13	2019-05-29	71.377 mi
Registration #14	2019-05-29	71.377 mi
Registration #15	2019-05-29	71.377 mi
Registration #16	2019-05-29	71.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1480 mm
Length	4280 mm
Wheel base	2650 mm
Kerb weight	1293 kg
Max. allowed weight	1720 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	G4FABZ349089
---------------	--------------