



report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER SDV8 VOGUE
Colour	Black
Year of manufacture	2013
Top speed	135 mph
0 - 100 km/h	6.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	250 kW / 341 HP / 339 BHP
Max. torque	700 Nm at 1.700 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	37.2 mpg
Consumption combined	32.5 mpg
CO2 emission	229 g/km
CO2 label	L





## Internet history

## Entry 3

Date	2023-12-05
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

## Entry 2

Date	2023-10-18
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

## Entry 1

Date	2021-02-01
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-10
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	18
Total items failed	2

MOT #11	2024-04-11 10:52
MOT test number	456279295197
Result	✓ Passed
Next expiry date	2025-04-10

MOT #10	2023-03-23 14:47
MOT test number	976998084592
Result	✓ Passed

MOT #9	2022-03-23 15:49
MOT test number	329017073075
Result	✓ Passed

MOT #8	2021-04-08 11:37
MOT test number	821767239346
Result	✓ Passed
Advice	Coolant leak
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2021-04-08 10:27**MOT test number** 426430176746**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Coolant leak**MOT #6** 2019-11-29 13:03**MOT test number** 323096386723**Result** ✓ Passed**Advice** Under shields.**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine cover.**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2018-11-27 10:42**MOT test number** 842202065773**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2018-11-26 16:04**MOT test number** 238137817965**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2017-12-04 15:22**MOT test number** 597725873838**Result** ✓ Passed**MOT #2** 2017-03-29 14:50**MOT test number** 808271717964**Result** ✓ Passed**MOT #1** 2016-03-30 09:09**MOT test number** 601560265049**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
6 October 2023

✓

MOT

Expires:  
10 April 2025

Tax status	Expired at 6 October 2023
Days left	206 days too late
MOT expiry date	10 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-26
Last registration	2024-04-11
Complete history	<a href="#">See info</a>



Registration #1	2013-03-26	20 mi
Registration #2	2016-03-30	29.850 mi
Registration #3	2017-03-29	42.069 mi
Registration #4	2017-12-04	46.313 mi
Registration #5	2018-11-26	54.972 mi
Registration #6	2018-11-27	54.972 mi
Registration #7	2019-11-29	62.161 mi
Registration #8	2019-11-29	62.161 mi
Registration #9	2019-11-29	62.161 mi
Registration #10	2019-11-29	62.161 mi
Registration #11	2019-11-29	62.161 mi
Registration #12	2019-11-29	62.161 mi
Registration #13	2019-11-29	62.161 mi
Registration #14	2019-11-29	62.161 mi
Registration #15	2019-11-29	62.161 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2220 mm
Height	1867 mm
Length	4998 mm
Wheel base	2922 mm
Kerb weight	2360 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	105 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0029133448DT