





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 MILLESIM
Colour	Yellow
Year of manufacture	2010
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 3

Date 2021-09-08

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-07-27
------	------------


Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-10

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

✓ Passed

M		history
	\cup	IIISLUIV

Result

MOT expiry date	2024-09-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	6
MOT #13	2023-09-22 14:58
MOT test number	559862989021
Result	✓ Passed
Next expiry date	2024-09-21
MOT #12	2022-11-04 10:42
MOT test number	385535918926

MOT #11	2021-11-05 11:39
MOT test number	538667682409
Result	✓ Passed

MOT #10	2020-11-04 11:06
MOT test number	737932828582
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Rear Exhaust has a major leak of exhaust gases Back box join (6.1.2 (a))

Fail Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Fail Offside Brake pipe excessively corroded Front to rear (1.1.11 (c))

MOT #8

MOT test number

350825303933

Result

Advice Offside Rear Brake pipe corroded, covered in grease or other material Front to Back (1.1.11 (c))

Advice Exhaust Hangers Deteriorating

2019-04-26 08:02 **MOT #7** 154164629239 **MOT** test number Result × Failed **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Front Service brake binding but not excessively (1.2.1 (f)) **Advice** Offside Rear Brake pipe corroded, covered in grease or other material Front to Back (1.1.11 (c)) Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) **Advice Exhaust Hangers Deteriorating** Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Front Brakes imbalanced across an axle Uneven Application (1.2.1 (b) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6	2018-04-21 14:30
MOT test number	719523773510
Result	✓ Passed
MOT #5	2017-04-15 12:17
MOT test number	130279206392
Result	✓ Passed
MOT #4	2016-04-25 09:21
MOT test number	530521792493
Result	✓ Passed
Advice Tyre worn close to the legal limit Both front (4.1.E.1) Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2015-04-13 10:11
MOT test number	249723205468
Result	✓ Passed
MOT #2	2014-04-11 15:53
MOT test number	207071404487
Result	✓ Passed
Notice Nail in nearside rear tyre	
Notice Slight perishing of both rear tyre treads.	

MOT #1	2013-05-02 13:30
MOT test number	179802923120
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expires: 21 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

ton	hic)wner	\sim
STOI	nıs	JWner	

	•	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
manners and the same and the sa		

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	NK NA	
Plate since		
Current registration	UK NA	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-30
Last registration	2023-09-22
Complete history	See info



Registration #1	2010-04-30	14 mi
Registration #2	2013-05-02	23.841 mi
Registration #3	2014-04-11	29.755 mi
Registration #4	2015-04-13	39.401 mi
Registration #5	2016-04-25	49.108 mi
Registration #6	2017-04-15	58.277 mi
Registration #7	2018-04-21	67.662 mi
Registration #8	2019-04-26	74.888 mi
Registration #9	2019-04-26	74.888 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionin
S0295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1