



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	Black
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-02
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-26
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #14 2024-02-27 12:32

MOT test number 295505533450

Result ✓ Passed

Next expiry date 2025-02-26

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2022-12-07 09:47

MOT test number 666505015163

Result ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2021-12-09 17:10**MOT test number** 114976652625**Result** ✓ Passed**MOT #11** 2021-12-08 15:24**MOT test number** 998179341252**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #10** 2020-11-03 15:06**MOT test number** 167991684803**Result** ✓ Passed**MOT #9** 2019-11-01 11:31**MOT test number** 695246275518**Result** ✓ Passed**MOT #8** 2018-11-07 10:10**MOT test number** 859835575128**Result** ✓ Passed**MOT #7** 2018-01-15 11:56**MOT test number** 866505380698**Result** ✓ Passed**MOT #6** 2017-05-25 13:44**MOT test number** 667769577945**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights

**MOT #5** 2017-05-25 13:44**MOT test number** 361715237302**Result** ✗ Failed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Pass with rectification** Nearside Front Electrical wiring insecure speed sensor wire (1.9.2a)**MOT #4** 2016-05-31 08:02**MOT test number** 101772349831**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-05-27 13:56**MOT test number** 436150619896**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2015-05-28 17:00**MOT test number** 806188645107**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #12015-05-28 10:42

MOT test number766758245161

Result

Failed

NoticeEngine covers fitted obscuring some components in the engine bay

NoticeUnder-trays fitted obscuring some underside components

FailOffside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
26 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-05-30
Last registration	2024-02-27
Complete history	See info



Registration #1	2012-05-30	16 mi
Registration #2	2015-05-28	25.283 mi
Registration #3	2015-05-28	25.284 mi
Registration #4	2016-05-27	39.013 mi
Registration #5	2016-05-31	39.102 mi
Registration #6	2017-05-25	52.329 mi
Registration #7	2017-05-25	52.329 mi
Registration #8	2018-01-15	58.720 mi
Registration #9	2019-05-27	59.377 mi
Registration #10	2019-05-27	59.377 mi
Registration #11	2019-05-27	59.377 mi
Registration #12	2019-05-27	59.377 mi
Registration #13	2019-05-27	59.377 mi
Registration #14	2019-05-27	59.377 mi
Registration #15	2019-05-27	59.377 mi
Registration #16	2019-05-27	59.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	2259719