



report date: 2024-03-28

## General information

Make	VOLVO
Model	S60 T SE S60
Colour	Grey
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	180 BHP
Max. torque	240 Nm at 5.300 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.7 mpg
CO2 emission	212 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-11
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-12
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	14
Total items failed	2

MOT #18	2023-10-12 17:39
MOT test number	822181799649
Result	✓ Passed
Next expiry date	2024-10-12

MOT #17	2023-10-12 17:39
MOT test number	288610597428
Result	✗ Failed
<b>Pass with rectification</b> Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #16	2022-10-04 13:57
MOT test number	400433436351
Result	✓ Passed
<b>Advice</b> Front wipers worn	
<b>Advice</b> Suspension arm pin or bush worn but not resulting in excessive movement both side front & both side rear (5.3.4 (a) (i))	
<b>Advice</b> Rear anti roll bar & rear spring corroded	
<b>Advice</b> Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
<b>Advice</b> Slight play in steering joints	

**MOT #15** 2021-10-06 10:00**MOT test number** 971875607877**Result** ✓ Passed**MOT #14** 2020-10-13 16:07**MOT test number** 535312115651**Result** ✓ Passed**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #13** 2020-10-05 15:31**MOT test number** 239738031374**Result** ✗ Failed**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #12** 2019-10-10 11:05**MOT test number** 387836217564**Result** ✓ Passed**MOT #11** 2019-01-09 09:20**MOT test number** 841218900409**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2018-01-03 11:14**MOT test number** 898037301760**Result** ✓ Passed

**MOT #9** 2017-01-25 12:57**MOT test number** 906213480791**Result** ✓ Passed**MOT #8** 2016-01-18 10:43**MOT test number** 226438098903**Result** ✓ Passed**MOT #7** 2015-01-23 11:27**MOT test number** 518403825020**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-01-27 10:01**MOT test number** 378507324090**Result** ✓ Passed**MOT #5** 2014-01-27 10:01**MOT test number** 885957924058**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp not working (1.1.C.1d)**MOT #4** 2013-02-11 15:48**MOT test number** 168032643014**Result** ✓ Passed



MOT #3	2012-02-17 11:25
MOT test number	115088542006
Result	✓ Passed
MOT #2	2011-02-28 16:21
MOT test number	588619751035
Result	✓ Passed
MOT #1	2010-03-04 09:32
MOT test number	992313360024
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
12 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	12 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>DU07RUO</b>
Plate since	2019-09-28
Current registration	<b>DU07RUO</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-09
Last registration	2023-10-12
Complete history	<a href="#">See info</a>



Registration #1	2007-03-09	6 mi
Registration #2	2010-03-04	10.966 mi
Registration #3	2011-02-28	24.078 mi
Registration #4	2012-02-17	41.793 mi
Registration #5	2013-02-11	55.972 mi
Registration #6	2014-01-27	66.233 mi
Registration #7	2015-01-23	71.765 mi
Registration #8	2016-01-18	76.724 mi
Registration #9	2017-01-25	80.441 mi
Registration #10	2018-01-03	82.641 mi
Registration #11	2019-01-03	85.277 mi
Registration #12	2020-01-03	88.277 mi
Registration #13	2021-01-03	91.277 mi
Registration #14	2022-01-03	94.277 mi
Registration #15	2023-01-03	97.277 mi
Registration #16	2024-01-03	100.277 mi
Registration #17	2025-01-03	103.277 mi
Registration #18	2026-01-03	106.277 mi
Registration #19	2027-01-03	109.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1428 mm
Length	4576 mm
Wheel base	2715 mm
Kerb weight	1427 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	4169079
---------------	---------