



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | FIAT |
| Model | PANDA ACTIVE |
| Colour | White |
| Year of manufacture | 2008 |
| Top speed | 93 mph |
| 0 - 60 mph | 15.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 54 BHP |
| Max. torque | 87 Nm at 2.750 rpm |
| Engine capacity | 1.108 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 132 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-06 |
| Pictures | 5 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-22 |
| MOT pass rate | 68 % |
| MOT passed | 13 |
| Failed MOT tests | 6 |
| Total advice items | 47 |
| Total items failed | 7 |

| | |
|------------------|--|
| MOT #19 | 2023-10-23 13:13 |
| MOT test number | 420345119597 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-22 |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) |
| Minor | Front Windscreen wiper blade defective (3.4 (b) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge STRONG ADVICE (5.2.3 (e)) |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge STRONG ADVICE (5.2.3 (e)) |

**MOT #18**

2022-10-06 09:11

MOT test number

673175672516

Result

✓ Passed

- Advice** Both front wipers noisy/juddering but clear screen
- Advice** Centre to rear exhaust join clamp is missing - exhaust is secure
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge smooth on inner edge - rest of tread 2-3mm and is slightly stress cracked in tread (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Advice** Outer skin on rear exhaust silencer corroded and coming away
- Advice** Offside Front Tyre worn close to legal limit/worn on edge smooth on inner edge - rest of tread 3-4mm and is slightly stress cracked in tread (5.2.3 (e))
- Advice** Down pipe to centre exhaust join clamp partially corroded through

MOT #17

2021-10-06 16:29

MOT test number

328125722745

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge smooth on inner edge - rest of tread 3-4mm (5.2.3 (e))
- Advice** Centre to rear exhaust join clamp missing - exhaust secure
- Advice** Starter motor noisy when disengaging
- Advice** Offside Front Tyre worn close to legal limit/worn on edge smooth on inner edge - rest of tread 4mm (5.2.3 (e))
- Advice** Majority of outer skin on rear exhaust silencer missing - what remains is corroded
- Advice** Down pipe to centre exhaust join clamp partially corroded through

**MOT #16**

2021-10-06 11:46

MOT test number

174444104975

Result**✗ Failed****Fail** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Centre to rear exhaust join clamp missing - exhaust secure**Advice** Starter motor noisy when disengaging**Advice** Offside Front Tyre worn close to legal limit/worn on edge smooth on inner edge - rest of tread 4mm (5.2.3 (e))**Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Majority of outer skin on rear exhaust silencer missing - what remains is corroded**Advice** Down pipe to centre exhaust join clamp partially corroded through**Advice** Nearside Front Tyre worn close to legal limit/worn on edge smooth on inner edge - rest of tread 3-4mm (5.2.3 (e))**MOT #15**

2020-09-25 10:40

MOT test number

775358284872

Result**✓ Passed****Advice** Offside Rear Upper shock absorber bush splitting**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear silencer clamp missing**Advice** Rear silencer outer skin corroded

**MOT #14** 2020-09-25 08:12**MOT test number** 117692437802**Result** ✗ Failed

- Advice** Rear silencer clamp missing
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear silencer outer skin corroded
- Advice** Offside Rear Upper shock absorber bush splitting
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #13 2019-09-21 10:03**MOT test number** 569443487231**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust back box corroded and outer skin coming off
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2018-09-29 14:06**MOT test number** 508343243442**Result** ✓ Passed**MOT #11** 2017-10-06 15:09**MOT test number** 386806108264**Result** ✓ Passed**MOT #10** 2016-10-08 12:04**MOT test number** 140150550995**Result** ✓ Passed

**MOT #9** 2016-10-08 12:04**MOT test number** 866525655808**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #8** 2015-06-18 10:11**MOT test number** 267359665106**Result** ✓ Passed**MOT #7** 2014-06-25 10:16**MOT test number** 639426574149**Result** ✓ Passed**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Park lamp on**MOT #6** 2014-06-25 10:16**MOT test number** 508146174181**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Park lamp on**MOT #5** 2013-06-14 15:49**MOT test number** 238665163457**Result** ✓ Passed**Notice** Exhaust rear silencer corroded**Notice** Offside front and nearside rear tyres worn to 3mm

**MOT #4** 2013-06-14 09:36**MOT test number** 675575763106**Result** ✗ Failed**Notice** Exhaust rear silencer corroded**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Notice** Offside front and nearside rear tyres worn to 3mm**MOT #3** 2012-06-28 13:43**MOT test number** 786250882152**Result** ✓ Passed**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**MOT #2** 2012-06-26 09:46**MOT test number** 717298772107**Result** ✗ Failed**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside front tyre**MOT #1** 2011-06-20 14:35**MOT test number** 209161271474**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
22 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 32 |
| MOT expiry date | 22 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this FIAT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2008-06-30 |
| Last registration | 2023-10-23 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2008-06-30 | 10 mi |
| Registration #2 | 2011-06-20 | 13.317 mi |
| Registration #3 | 2012-06-26 | 17.458 mi |
| Registration #4 | 2012-06-28 | 17.501 mi |
| Registration #5 | 2013-06-14 | 21.936 mi |
| Registration #6 | 2013-06-14 | 21.936 mi |
| Registration #7 | 2014-06-25 | 29.143 mi |
| Registration #8 | 2015-06-18 | 34.796 mi |
| Registration #9 | 2016-10-08 | 36.693 mi |
| Registration #10 | 2016-10-08 | 36.693 mi |
| Registration #11 | 2016-10-08 | 36.693 mi |
| Registration #12 | 2016-10-08 | 36.693 mi |
| Registration #13 | 2016-10-08 | 36.693 mi |
| Registration #14 | 2016-10-08 | 36.693 mi |
| Registration #15 | 2016-10-08 | 36.693 mi |
| Registration #16 | 2016-10-08 | 36.693 mi |
| Registration #17 | 2016-10-08 | 36.693 mi |
| Registration #18 | 2016-10-08 | 36.693 mi |
| Registration #19 | 2016-10-08 | 36.693 mi |
| Registration #20 | 2016-10-08 | 36.693 mi |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1578 mm |
| Height | 1540 mm |
| Length | 3538 mm |
| Wheel base | 2299 mm |
| Kerb weight | 840 kg |
| Max. allowed weight | 1255 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 4575875 |