




report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 CDTI BITURBO S/S
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-06
Pictures	14
Listing price	<a href="#">View report</a>

One Owner  
From New



PLUS VAT



Please be aware that the advertised price for this commercial vehicle is plus 20% VAT.



Extended warranty  
available



Why not extend your warranty provided with any vehicle purchased.

For further details ask a member of our team to help.



33 Years  
Experience



Here at TVM, our helpful team have lots of experience in aiding you both during and after purchasing your vehicle.

Buy from the best, hassle free.



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-09
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	7
Total items failed	6

MOT #6	2023-07-10 09:55
MOT test number	706247139654
Result	✓ Passed
Next expiry date	2024-07-09
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5	2023-07-10 07:54
MOT test number	368865988827
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #4	2022-05-26 14:45
MOT test number	169274139798
Result	✓ Passed

MOT #3	2020-12-17 14:42
MOT test number	542894999944
Result	✓ Passed
Advice	Nearside Rear Nail in tyre And tread worn mishaped

**MOT #2**

2020-12-08 11:27

**MOT test number**

944605742168

**Result****✗ Failed**

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Nearside Front Brake hose excessively stretched Insecure (1.1.12 (b) (ii))
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Advice** Nearside Rear Nail in tyre And tread worn mishaped
- Fail** Upper Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #1**

2019-12-11 12:31

**MOT test number**

188752918142

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
9 July 2024

Tax status		Valid until 1 September
Days left		124
MOT expiry date		9 July 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>DN66LXO</b>
Plate since	2024-03-29
Current registration	 <b>DN66LXO</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-12-14
Last registration	2023-07-10
Complete history	<a href="#">See info</a>



Registration #1	2016-12-14	11 mi
Registration #2	2019-12-11	37.403 mi
Registration #3	2020-12-08	52.650 mi
Registration #4	2020-12-17	52.661 mi
Registration #5	2023-07-10	52.661 mi
Registration #6	2023-07-10	52.661 mi
Registration #7	2023-07-10	52.661 mi
Registration #8	2023-07-10	52.661 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1760 kg
Max. allowed weight	3040 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MH - C084191LQI