




report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	Blue
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-06
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-01
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	16
Total items failed	4

MOT #14	2024-04-18 16:17
MOT test number	497732863867
Result	✓ Passed
Next expiry date	2025-05-01
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Inner Play in steering rack inner joint(s)

MOT #13	2024-04-18 08:49
MOT test number	291563827690
Result	✗ Failed
Fail	Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Inner Play in steering rack inner joint(s)
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2023-05-02 10:09**MOT test number** 187263428902**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer edge of tread splitting (5.2.3 (d) (ii))**Advice** Advise covers under bonnet under car and on outer sills preventing full inspection**MOT #11** 2023-04-28 09:28**MOT test number** 557350864775**Result** ✗ Failed**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer edge of tread splitting (5.2.3 (d) (ii))**Advice** Advise covers under bonnet under car and on outer sills preventing full inspection**MOT #10** 2022-05-19 09:28**MOT test number** 577698397847**Result** ✓ Passed**Advice** Under trays fitted obscuring some components**MOT #9** 2022-05-19 09:28**MOT test number** 383473811350**Result** ✗ Failed**Advice** Under trays fitted obscuring some components**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #8** 2021-05-20 09:18**MOT test number** 903382468881**Result** ✓ Passed**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing edge (5.2.3 (d) (ii))

**MOT #7** 2020-06-08 13:30**MOT test number** 363505618892**Result** ✓ Passed**Minor** Rear Registration plate lamp insecure (4.7.1 (c) (i))**MOT #6** 2020-06-08 12:10**MOT test number** 892307489189**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Rear Registration plate lamp insecure (4.7.1 (c) (i))**MOT #5** 2019-06-14 11:01**MOT test number** 786976798492**Result** ✓ Passed**MOT #4** 2018-06-16 09:11**MOT test number** 365585619640**Result** ✓ Passed**MOT #3** 2017-07-08 09:18**MOT test number** 830654814391**Result** ✓ Passed**Advice** Nearside Front tyre tread bald on inner edge.**MOT #2** 2016-07-30 08:51**MOT test number** 711355687551**Result** ✓ Passed



MOT #1	2015-08-01 10:31
MOT test number	507643415241
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 November 2024

✓  
**MOT**

**Expires:**  
1 May 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	1 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-28
Current registration	 
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-09-26
Last registration	2024-04-18
Complete history	<a href="#">See info</a>



Registration #1	2012-09-26	7 mi
Registration #2	2015-08-01	21.161 mi
Registration #3	2016-07-30	24.829 mi
Registration #4	2017-07-08	28.893 mi
Registration #5	2018-06-16	33.707 mi
Registration #6	2019-06-14	36.834 mi
Registration #7	2020-06-08	41.666 mi
Registration #8	2020-06-08	41.666 mi
Registration #9	2020-06-08	41.666 mi
Registration #10	2020-06-08	41.666 mi
Registration #11	2020-06-08	41.666 mi
Registration #12	2020-06-08	41.666 mi
Registration #13	2020-06-08	41.666 mi
Registration #14	2020-06-08	41.666 mi
Registration #15	2020-06-08	41.666 mi
Registration #16	2020-06-08	41.666 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1345 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	73078350
---------------	----------