



report date: 2024-03-28

General information

Make	NISSAN
Model	MICRA ACENTA
Colour	Silver
Year of manufacture	2014
Top speed	101 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed CVT

Engine & fuel consumption

Power	79 BHP
Max. torque	142 Nm at 4.400 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 2

Date	2023-12-11
Pictures	8



source: g3remarketing.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	32
Total items failed	5

MOT #10	2023-09-09 11:32
MOT test number	148705310892
Result	✓ Passed
Next expiry date	2024-10-06
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on outer edge 175/60X15 (5.2.3 (e))

MOT #9	2023-09-09 11:32
MOT test number	905071891309
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on outer edge 175/60X15 (5.2.3 (e))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #8**

2022-10-07 12:26

**MOT test number**

529994190565

**Result**

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #7**

2022-09-16 15:42

**MOT test number**

928588927554

**Result**

✗ Failed

- Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Front Windscreen wiper blade defective both front wipers smearing (3.4 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #6**

2021-09-20 15:32

**MOT test number**

360534405062

**Result**

✓ Passed

**MOT #5** 2020-09-28 13:01**MOT test number** 524733707734**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #4** 2019-09-10 11:01**MOT test number** 693770941484**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement 'front bush' (5.3.4 (a) (i))**MOT #3** 2019-09-10 08:45**MOT test number** 804657048590**Result** ✗ Failed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Fail** Nearside Front Suspension arm pin or bush excessively worn 'front bush' (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 175/60/15 (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 175/60/15 (5.2.3 (d) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement 'front bush' (5.3.4 (a) (i))



MOT #2	2018-09-07 11:16
MOT test number	359448847455
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #1	2017-09-14 08:53
MOT test number	879373460179
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
6 October 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	368
<b>MOT expiry date</b>	6 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-23
Last registration	2023-09-09
Complete history	<a href="#">See info</a>



Registration #1	2014-09-23	20 mi
Registration #2	2017-09-14	43.941 mi
Registration #3	2018-09-07	62.251 mi
Registration #4	2019-09-10	80.709 mi
Registration #5	2019-09-10	80.710 mi
Registration #6	2020-09-28	84.527 mi
Registration #7	2020-09-28	84.527 mi
Registration #8	2020-09-28	84.527 mi
Registration #9	2020-09-28	84.527 mi
Registration #10	2020-09-28	84.527 mi
Registration #11	2020-09-28	84.527 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1665 mm
Height	1520 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	945 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	767078B
---------------	---------