





report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI S LINE
Colour	Grey
Year of manufacture	2008
Top speed	128 mph
0 - 60 mph	9.8 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.986 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date	2021-01-27	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-09-28
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	32
Total items failed	10

MOT #21	2023-09-29 11:57
MOT test number	566167203688
Result	✓ Passed
Next expiry date	2024-09-28
Advice Offside Front wheel and cvboot has greese on	
Advice Rear subframe corroding	

MOT #20	2022-09-06 08:10
MOT test number	725154523583
Result	✓ Passed
Advice Exhaust corroded	

MOT #19		2021-08-18 11:43
MOT test	number	215348881024
Result		✓ Passed
Advice bushes (5	Nearside Front Suspension arm pin or bush worn but not resulting in excess .3.4 (a) (i))	sive movement top arm
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement top arm bushes (5.3.4 (a) (i))		
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #18 2021-08-10 11:29

MOT test number 257081591273

Result X Failed

Fail Nearside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement top arm bushes (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Fail Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement top arm bushes (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17 2020-09-04 08:01

MOT test number 561655259574

Advice Temporary fuel cap fitted

Advice Upper Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2019-07-30 11:05

MOT test number 956873576084

Result \rightarrow Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Temporary fuel cap fitted

CarCheck.co.uk page 4/14



MOT #15 2019-07-26 12:03

MOT test number 801412519687

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))

Fail Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Temporary fuel cap fitted

MOT #14 2018-07-20 11:10

MOT test number 186906943749

Result

Passed

MOT #13 2017-06-30 14:58

MOT test number 521273930844

Result
✓ Passed

MOT #12 2017-06-30 09:22

MOT test number 279584799433

Result × Failed

Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #11 2016-07-15 15:41

MOT test number 491806391784

Result ✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #10

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9

MOT test number

Result

Pass with rectification

Nearside Registration plate lamp not working (1.1.C.1d)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8

MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Notice Sill covers fitted

MOT test number
709881114265

Result
Notice Sill covers fitted

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 6/14



report date: 2024-03-29

 MOT #6
 2013-10-28 15:28

 MOT test number
 659491903367

 Result
 ✓ Passed

 MOT #5
 2013-05-21 09:11

 MOT test number
 685421543190

Result ✓ Passed

MOT #4 2012-05-22 10:55

MOT test number 536393742169

Notice Front tyre's 2mm

MOT #3 2012-05-21 12:35

MOT test number 219332342472

Result × Failed

Notice Front tyre's 2mm

Fail Nearside Rear coil spring incomplete (2.4.C.1a)

MOT #2 2011-06-15 11:39

MOT test number 268176461182

MOT #1 2011-06-14 17:19

MOT test number 679135861150

Result X Failed

Notice BATTERY U/S

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Notice TRACTION CONTROL LIGHT ON.

CarCheck.co.uk page 7/14



Tax & MOT check





Expires: 28 September 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	28 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e when misterly	
For how long did the current and previous owner(s) have this AUDI? How many owners defect it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-02-19
Last registration	2023-09-29
Complete history	See info



Registration #1	2008-02-19	13 mi
Registration #2	2011-06-14	24.599 mi
Registration #3	2011-06-15	24.599 mi
Registration #4	2012-05-21	34.019 mi
Registration #5	2012-05-22	34.025 mi
Registration #6	2013-05-21	65.229 mi
Registration #7	2013-10-28	46.224 mi
Registration #8	2014-07-30	50.674 mi
Registration #9	2015-07-07	55.928 mi
Registration #10	2016-07-15	60.782 mi
Registration #11	2017-06-30	66.669 mi
Registration #12		77.777 es
Registration #13		71.777 es
Registration #14		77.777 es
Registration #15		71.777 es
Registration #16		77.777 es
Registration #17		71.777 es
Registration #18		71.777 es
Registration #19		10,777 mg
Registration #20		0.074

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditionir
S0295	
S0482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2642 mm
Kerb weight	1490 kg
Max. allowed weight	2020 kg

Additional information

		_
Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 14	/14

Number of axles 2

Engine number BRE 167723