



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D DRIVE R-DESIGN
Colour	Grey
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	175 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G








Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-24
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	31
Total items failed	8

MOT #17 2024-03-25 11:51

MOT test number 890946017435

Result ✓ Passed

Next expiry date 2025-03-24

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2023-03-24 08:48

MOT test number 490173287089

Result ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #15 2023-03-17 13:46

MOT test number 104078668756

Result ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #14** 2021-12-24 09:00**MOT test number** 492953896108**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-12-28 14:11**MOT test number** 745005867789**Result** ✓ Passed**MOT #12** 2019-12-07 12:59**MOT test number** 225556842898**Result** ✓ Passed**Advice** Electrical tow socket deteriorated**Advice** Offside headlamp lens deteriorated**MOT #11** 2018-12-10 15:29**MOT test number** 755222957796**Result** ✓ Passed**Advice** Tow electric socket adaptor in poor condition**MOT #10** 2018-12-08 10:03**MOT test number** 551117367338**Result** ✗ Failed**Fail** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Tow electric socket adaptor in poor condition**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #9** 2017-12-02 09:31**MOT test number** 187625018103**Result** ✓ Passed**Advice** Engine and under covers fitted**Advice** Engine and under covers fitted**MOT #8** 2016-12-11 10:59**MOT test number** 709730652928**Result** ✓ Passed**Advice** Under bonnet covers and undertrays fitted restricting view**MOT #7** 2016-12-11 10:59**MOT test number** 404790599621**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Under bonnet covers and undertrays fitted restricting view**MOT #6** 2015-11-30 08:16**MOT test number** 784495869185**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2015-11-21 11:29**MOT test number** 745653891871**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2014-12-10 14:50**MOT test number** 846104344358**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-01-17 14:40**MOT test number** 387117014051**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-01-17 14:40**MOT test number** 387267014079**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1 2013-01-04 14:34

MOT test number 425074303053

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-19
Last registration	2024-03-25
Complete history	See info



Registration #1	2010-03-19	17 mi
Registration #2	2013-01-04	36.327 mi
Registration #3	2014-01-17	58.288 mi
Registration #4	2014-12-10	71.315 mi
Registration #5	2015-11-21	85.740 mi
Registration #6	2015-11-30	86.056 mi
Registration #7	2016-12-11	101.700 mi
Registration #8	2016-12-11	101.700 mi
Registration #9	2017-12-02	116.681 mi
Registration #10	2019-05-20	151.377 mi
Registration #11	2019-05-20	151.377 mi
Registration #12	2019-05-20	151.377 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi
Registration #16	2019-05-20	151.377 mi
Registration #17	2019-05-20	151.377 mi
Registration #18	2019-05-20	151.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	777208