



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Black
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-08
Pictures	11
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #16** 2020-11-10 14:00**MOT test number** 773947785683**Result** ✓ Passed**Next expiry date** 2021-11-09

- Advice** Underside of vehicle coated with underseal
- Advice** Coil spring corroded all (5.3.1 (b) (i))
- Advice** Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))

MOT #15 2019-10-02 14:19**MOT test number** 392728694880**Result** ✓ Passed

- Advice** Nearside Rear tyre worn on inside edge
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear tyre worn on inside edge

**MOT #14**

2019-09-02 08:32

MOT test number

110140083136

Result

✗ Failed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Brake pipe excessively corroded rear section offside front to rear (1.1.11 (c))

Advice Nearside Rear tyre worn on inside edge

Fail Offside Inner Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Brake pipe excessively corroded rear section nearside front to rear (1.1.11 (c))

Fail Nearside Inner Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Advice Offside Rear tyre worn on inside edge

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2018-08-04 10:22

MOT test number

343833153948

Result

✓ Passed

Advice Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Suspension component pin or bush slightly worn wishbone rear bush perished (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Suspension component pin or bush slightly worn wishbone rear bush perished (5.3.4 (a) (i))



MOT #12 2017-08-02 11:02

MOT test number 264444456058

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit 3MM worn slightly on edges (4.1.E.1)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front dust covers on shockers split

Advice Offside Front Tyre worn close to the legal limit 3.5MM worn slightly on edges (4.1.E.1)

Advice Central Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #11 2016-05-25 10:23

MOT test number 701544486469

Result ✓ Passed

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #10 2016-05-25 10:23

MOT test number 899837547688

Result ✗ Failed

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Pass with rectification Offside Headlamp aim too low (1.8)

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #9** 2015-06-03 13:57**MOT test number** 217534455149**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2014-05-09 10:32**MOT test number** 908019624199**Result** ✓ Passed**MOT #7** 2014-05-08 11:05**MOT test number** 196088724153**Result** ✗ Failed**Fail** Nearside Front Wheel nut(s) missing (4.2.A.1e)**Fail** Nearside Rear Wheel nut(s) missing (4.2.A.1e)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)**Fail** Offside Rear Wheel nut(s) missing (4.2.A.1e)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2013-05-03 11:51**MOT test number** 256213823110**Result** ✓ Passed

**MOT #5** 2012-04-27 09:31**MOT test number** 858918212183**Result** ✓ Passed**MOT #4** 2011-05-07 09:14**MOT test number** 597967021156**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Advise o/s wiper**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-05-24 11:33**MOT test number** 221704940193**Result** ✓ Passed**MOT #2** 2010-05-21 09:18**MOT test number** 473391940174**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front registration plate insecure (6.3.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-05-18 09:17**MOT test number** 181528639108**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-04-28
Last registration	2020-11-10
Complete history	See info



Registration #1	2006-04-28	10 mi
Registration #2	2009-05-18	46.885 mi
Registration #3	2010-05-21	59.622 mi
Registration #4	2010-05-24	59.624 mi
Registration #5	2011-05-07	70.580 mi
Registration #6	2012-04-27	82.501 mi
Registration #7	2013-05-03	95.316 mi
Registration #8	2014-05-08	98.987 mi
Registration #9	2014-05-09	98.987 mi
Registration #10	2015-05-09	98.987 mi
Registration #11	2015-05-09	98.987 mi
Registration #12	2015-05-09	98.987 mi
Registration #13	2015-05-09	98.987 mi
Registration #14	2015-05-09	98.987 mi
Registration #15	2015-05-09	98.987 mi
Registration #16	2015-05-09	98.987 mi
Registration #17	2015-05-09	98.987 mi
Registration #18	2015-05-09	98.987 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1585 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0082158