



DK090AE


report date: 2024-03-29

General information

Make	AUDI
Model	ALLROAD TDI ALLROAD TDV QUATTRO
Colour	Grey
Year of manufacture	2009
Top speed	143 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	233 BHP
Max. torque	450 Nm at 1.400 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.1 mpg
CO2 emission	232 g/km
CO2 label	L






Internet history

Entry 2

Date	2021-10-30
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-06
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-14
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #17	2024-04-15 09:31
MOT test number	472966160379
Result	✓ Passed
Next expiry date	2025-04-14
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #16	2023-04-05 08:16
MOT test number	189565759461
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #15	2022-04-07 08:23
MOT test number	776225814927
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2021-03-26 15:34
MOT test number	359015776171
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-03-26 11:36**MOT test number** 719672125257**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2020-03-12 14:23**MOT test number** 329774763091**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2019-04-09 10:50**MOT test number** 430137692979**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-04-09 09:33**MOT test number** 534122500837**Result** ✓ Passed**MOT #9** 2017-03-03 15:17**MOT test number** 287058441139**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #8** 2017-03-01 12:40**MOT test number** 622579100145**Result** ✗ Failed**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #7** 2016-03-21 12:30**MOT test number** 879357347854**Result** ✓ Passed**MOT #6** 2016-03-18 10:46**MOT test number** 115295637359**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Outer Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2015-03-31 14:47**MOT test number** 377380595001**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-02-25 14:58**MOT test number** 976276854080**Result** ✓ Passed

**MOT #3** 2014-02-21 15:35**MOT test number** 455102754050**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2013-02-21 13:40**MOT test number** 888602553063**Result** ✓ Passed**Advice** Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1** 2012-02-21 11:31**MOT test number** 876652252029**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 April 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-01
Last registration	2024-04-15
Complete history	See info



Registration #1	2009-03-01	25 mi
Registration #2	2012-02-21	46.518 mi
Registration #3	2013-02-21	61.865 mi
Registration #4	2014-02-21	73.025 mi
Registration #5	2014-02-25	73.122 mi
Registration #6	2015-03-31	84.737 mi
Registration #7	2016-03-18	96.635 mi
Registration #8	2016-03-21	96.635 mi
Registration #9	2017-03-01	106.580 mi
Registration #10	2017-03-03	106.632 mi
Registration #11	2018-03-01	116.580 mi
Registration #12	2018-03-01	116.580 mi
Registration #13	2018-03-01	116.580 mi
Registration #14	2018-03-01	116.580 mi
Registration #15	2018-03-01	116.580 mi
Registration #16	2018-03-01	116.580 mi
Registration #17	2018-03-01	116.580 mi
Registration #18	2018-03-01	116.580 mi
Registration #19	2018-03-01	116.580 mi
Registration #20	2018-03-01	116.580 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1862 mm
Height	1519 mm
Length	4934 mm
Wheel base	2833 mm
Kerb weight	1880 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ASB152257