





report date: 2024-03-28

### General information

Make	BMW
Model	Z4 Z4 SDRIVE23I ROADSTER
Colour	Brown
Year of manufacture	2010
Top speed	151 mph
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	201 BHP
Max. torque	250 Nm at 2.750 rpm
Engine capacity	2.497 сс
Cylinders	6
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	33.2 mpg
CO2 emission	192 g/km
CO2 label	ı



CarCheck.co.uk page 1/13



HN10FNT report date: 2024-03-28

### Internet history

Entry	1

Date	2021-09-07
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-07-03
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	11
Total items failed	4

MOT #18	2023-07-04 13:12
MOT test number	904390777857
Result	✓ Passed
Next expiry date	2024-07-03

MOT #17	2023-07-04 12:01
MOT test number	420386332441
Result	<b>X</b> Failed
<b>DANGEROUS</b> Nearside Front Road wheel more than one fixing missing (5.2.1 (a) (i	ii))
Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))	

MOT #16	2022-05-24 13:44
MOT test number	595924647416
Result	✓ Passed

MOT #15	2021-11-24 14:28
MOT test number	209804288508
Result	✓ Passed

MOT #14	2021-04-19 10:11
MOT test number	296073472019
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2021-04-19 10:11

**MOT test number** 411928079977

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

(ii))

**MOT #12** 2020-06-16 15:49

**MOT test number** 207280218930

Result \( \sqrt{Passed} \)

**MOT #11** 2020-06-16 15:43

**MOT test number** 410575904634

**Result** X Failed

**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2020-06-16 10:00

MOT test number 236384726058

**Result** X Failed

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2019-04-26 11:09

MOT test number 225724654025

**Result** ✓ Passed

CarCheck.co.uk page 4/13



Result

**HN10FNT** 

report date: 2024-03-28

**X** Failed

MOT #8 2017-11-07 14:08

**MOT test number** 376975566738

Result Passed

Advice Both front tyres worn on outer edge

MOT #7 2017-11-03 12:43

**MOT test number** 281790568437

**Advice** Offside Rear Tyre worn close to the legal limit very close to failure (4.1.E.1)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Both front tyres worn on outer edge

MOT #6 2016-11-09 18:12

**MOT test number** 611056425990

**Result** 
✓ Passed

MOT #5 2016-04-29 14:29

**MOT test number** 267209779241

**Result** ✓ Passed

**MOT #4** 2015-04-27 15:48

MOT test number 868007515112

**Notice** Both rear tyres low both front tyres wearing on edges

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3	2015-04-27 10:10
MOT test number	189947115133
Result	<b>×</b> Failed
Notice Both rear tyres low both front tyres wearing on edges  Fail Offside Front position lamp(s) not working (1.1.A.3b)	

MOT #2	2014-05-02 10:29
MOT test number	335672424118
Result	✓ Passed
MOT #1	2013-05-03 12:09
MOT test number	928183223198
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



HN10FNT report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	3 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NIK NIK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-05-06
Last registration	2023-07-04
Complete history	See info



Registration #1	2010-05-06	18 mi
Registration #2	2013-05-03	13.588 mi
Registration #3	2014-05-02	23.821 mi
Registration #4	2015-04-27	36.289 mi
Registration #5	2015-04-27	36.295 mi
Registration #6	2016-04-29	53.213 mi
Registration #7	2016-11-09	60.178 mi
Registration #8	2017-11-03	72.982 mi
Registration #9	2017-11-07	73.047 mi
Registration #10	2019-04-26	86.824 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		71.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		0.70 es
Registration #20		71.777 es

More info >

CarCheck.co.uk page 12/13



HN10FNT report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
50501	
50566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1790 mm
Height	1291 mm
Length	4239 mm
Wheel base	2496 mm
Kerb weight	1505 kg
Max. allowed weight	1760 kg

### Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 13

Number of axles2Engine number07537353