





General information

Make	KIA
Model	PICANTO SR7
Colour	White
Year of manufacture	2015
Top speed	98 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP	
Max. torque	95 Nm at 3.500 rpm	
Engine capacity	998 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	48.7 mpg	
Consumption extra urban	74.3 mpg	
Consumption combined	62.8 mpg	
CO2 emission	105 g/km	
CO2 label	В	





Internet history	
Entry 1	
Date	2021-06-15
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #7	2023-06-30 13:41
MOT test number	473680730932
Result	✓ Passed
Next expiry date	2024-07-04

МОТ #6	2022-06-21 14:55
MOT test number	807989844474
Result	🗸 Passed
Advice TPMS light illuminated but not indicating a fault	
Advice Parking brake efficiency only just met. It would appear that the braking sy adjustment or repair. (1.4.2 (a) (i))	rstem requires
Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice Offside Side repeater slightly discoloured (4.4.3 (a))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #5		2022-06-21 14:55	
MOT test number		219197516665	
Result		🗙 Failed	
Pass with rectificat	tion Offside Windscreen wiper does not clear the winds	screen effectively (3.4 (b) (ii))	
Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))			
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))			
Advice TPMS light illuminated but not indicating a fault			
Advice Offside Sid	Advice Offside Side repeater slightly discoloured (4.4.3 (a))		
Advice Nearside F	Rear Tyre slightly damaged (5.2.3 (d) (ii))		
Advice Offside Re	ear Brake disc worn, pitted or scored, but not seriously we	akened (1.1.14 (a) (ii))	

MOT #4	2021-07-05 08:25
MOT test number	954737555417
Result	✓ Passed

MOT #3	2020-09-08 10:05
MOT test number	131238054962
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #2	2019-09-10 10:45
MOT test number	726214088875
Result	✓ Passed

MOT #1	2018-09-12 13:26
MOT test number	601734954535
Result	✓ Passed



Tax & MOT check

Tax due: 1 July 2024	✓ Taxed	Expires: 4 July 2024	✓ мот
Tax status			Valid until 1 July
Days left			63
MOT expiry date			4 July 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Anne
Туре	K K
Damage 2	AMPLE
Damage 2	e et - I - I
Date	S.
Category	AMPT
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-09-30
Last registration	2023-06-30
Complete history	<u>See info</u>



Registration #1	2015-09-30	14 mi
Registration #2	2018-09-12	11.880 mi
Registration #3	2019-09-10	15.187 mi
Registration #4	2020-09-08	17.750 mi
Registration #5		11.117 esi
Registration #6		11.177 esi
Registration #7		11.777 esi
Registration #8		11.177 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditionin
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	83%
Pedestrian	47%
Safety systems	43%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1595 mm
Height	1480 mm
Length	3595 mm
Wheel base	2385 mm
Kerb weight	1039 kg
Max. allowed weight	1400 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	G3LAFP115250