



BX6ISW0

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN
Colour	Grey
Year of manufacture	2012
Gearbox	-

Engine & fuel consumption

Engine capacity	1.380 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 2

Date 2022-07-30

Pictures 8

Listing price [View report](#)



source: [autoonline.co.uk](#)

Entry 1

Date 2022-05-13

Pictures 12

Listing price [View report](#)



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-03-15
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	38
Total items failed	2

MOT #5 2024-03-13 16:09

MOT test number 281523801538

Result ✓ Passed

Next expiry date 2025-03-15

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2024-03-11 09:58

MOT test number 912645505072

Result ✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #3

2023-03-01 17:19

MOT test number

624973670556

Result

✓ Passed

- Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Fuel cap washer slightly deteriorated
- Advice

Items removed from driver's view prior to test
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Front Tyre has a cut but not deep enough to reach the ply or cords cuts (5.2.3 (d) (i))
- Minor

Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords cuts (5.2.3 (d) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords cuts (5.2.3 (d) (i))

**MOT #2** 2023-03-01 11:45**MOT test number** 567687019012**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords cuts (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords cuts (5.2.3 (d) (i))
- Advice** Fuel cap washer slightly deteriorated
- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords cuts (5.2.3 (d) (i))

MOT #1 2022-03-16 16:56**MOT test number** 114831074669**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
15 March 2025

Tax status		Valid until 1 July
Days left		63
MOT expiry date		15 March 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BX61SWO
Plate since	2019-06-29
Current registration	 BX61SWO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	8
First mileage registration	2012-02-01
Last registration	2024-03-13
Complete history	See info



Registration #1	2012-02-01	17 mi
Registration #2	2022-03-16	38.375 mi
Registration #3	2012-02-01	38.375 mi
Registration #4	2012-02-01	38.375 mi
Registration #5	2012-02-01	38.375 mi
Registration #6	2012-02-01	38.375 mi
Registration #7	2012-02-01	38.375 mi
Registration #8	2012-02-01	38.375 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Additional information

Number of seats	5
Engine number	CAV