




report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S ECOFLEX
Colour	Silver
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-04-22
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-03
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	6

MOT #13	2023-08-02 08:47
MOT test number	548346226460
Result	✓ Passed
Next expiry date	2024-08-03

MOT #12	2022-08-04 13:16
MOT test number	329501494416
Result	✓ Passed

MOT #11	2022-08-04 09:24
MOT test number	453636807288
Result	✗ Failed
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #10	2021-10-04 12:24
MOT test number	231067363830
Result	✓ Passed



MOT #9	2021-10-01 16:01
MOT test number	922149284733
Result	✗ Failed
Fail	Brake pipe excessively corroded front to rear (1.1.11 (c))
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))

MOT #8	2020-09-16 08:32
MOT test number	870972035616
Result	✓ Passed
Advice	Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
Advice	Both front tyres perished

MOT #7	2019-04-02 09:18
MOT test number	122845038203
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Nail in tyre
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #6	2018-03-23 12:43
MOT test number	987773914357
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Offside Rear tyre perished



MOT #5	2017-04-04 09:18
MOT test number	400740267895
Result	✓ Passed
Advice	Offside Rear tyre perished
Advice	Offside Front brake pipe slightly corroded
Advice	Offside Front tyre perished and is close to limit (on 3mm)
Advice	Nearside Front tyre perished and close to limit (on 2.5mm)

MOT #4	2016-03-31 11:29
MOT test number	637842558385
Result	✓ Passed

MOT #3	2015-03-25 14:46
MOT test number	828504985056
Result	✓ Passed

MOT #2	2014-03-25 11:38
MOT test number	129324784495
Result	✓ Passed

MOT #1	2013-03-26 11:40
MOT test number	139175683081
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
3 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-04-15
Last registration	2023-08-02
Complete history	See info



Registration #1	2010-04-15	11 mi
Registration #2	2013-03-26	12.855 mi
Registration #3	2014-03-25	17.316 mi
Registration #4	2015-03-25	22.028 mi
Registration #5	2016-03-31	27.623 mi
Registration #6	2017-04-04	33.748 mi
Registration #7	2018-03-23	40.764 mi
Registration #8	2019-04-02	44.372 mi
Registration #9	2020-04-02	45.377 mi
Registration #10	2021-04-02	45.377 mi
Registration #11	2022-04-02	45.377 mi
Registration #12	2023-04-02	45.377 mi
Registration #13	2023-04-02	45.377 mi
Registration #14	2023-04-02	45.377 mi
Registration #15	2023-04-02	45.377 mi

[More info >](#)



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	975 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1089195