





### General information

Make	PEUGEOT
Model	3008 HDI ALLURE
Colour	Blue
Year of manufacture	2014
Top speed	114 mph
0 - 60 mph	13.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	127 g/km
CO2 label	D







## Internet history

Entry 1

Date

Pictures

2021-01-21

18

Listing price

View report









source: yesauto.com



# MOT history

MOT expiry date	2025-03-29
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #8		2022-02-02 10:48
MOT test	number	480411689663
Result		✓ Passed
Next expi	ry date	2023-02-15
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-02-16 12:53
MOT test number	972311390320
Result	✓ Passed
Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	

МОТ #6		2021-02-16 12:53
MOT test number		325859692900
Result		🗙 Failed
Minor Nearside Front W	indscreen wiper blade defective (3.4 (b) (i))	
<b>Pass with rectification</b> (b) (ii))	Offside Front Windscreen wiper does not clear the w	vindscreen effectively (3.4





MOT #5	2020-06-05 08:38
MOT test number	851281415564
Result	✓ Passed
Advice Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multip (4.7.1 (b) (i))	le lamps or light sources
MOT #4	2019-06-10 09:23
MOT test number	658350136036

✓ Passed	
Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (i))	
Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Offside Rear Tyre slightly damaged/cracking or perishing Slight flat spot on its inner tread 3.Y (5.2.3 (d) (ii))	
Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Nearside Rear Tyre slightly damaged/cracking or perishing Slight flat spot on its inner tread Y (5.2.3 (d) (ii))	
	✓ Passed Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (i)) Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i)) Offside Rear Tyre slightly damaged/cracking or perishing Slight flat spot on its inner tread .Y (5.2.3 (d) (ii)) Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i)) Nearside Rear Tyre slightly damaged/cracking or perishing Slight flat spot on its inner tread .Y (5.2.3 (d) (ii)) Nearside Rear Tyre slightly damaged/cracking or perishing Slight flat spot on its inner tread

MOT #3	2018-06-19 08:36
MOT test number	626469631924
Result	✓ Passed
Advice Nearside Rear Inner Road wheel slightly distorted Rim (5.2.2 (c) (i))	

MOT #2	2017-06-27 13:32
MOT test number	188037455230
Result	✓ Passed





MOT #1	2017-06-27 13:19
MOT test number	840410420308
Result	🗙 Failed
<b>Fail</b> Offside Front position lamp(s) not working (1.1.A.3b)	
FailNearside Front position lamp(s) not working (1.1.A.3b)	



Tax & MOT check

√ Taxed	✓ МОТ
Tax due: 1 July 2024	Expires: 29 March 2025
Tax status	Valid until 1 July
Days left	64
MOT expiry date	29 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
*********	
*******	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-06-13
Last registration	2022-02-02
Complete history	<u>See info</u>



Registration #1	2014-06-13	29 mi
Registration #2	2017-06-27	43.010 mi
Registration #3	2017-06-27	43.010 mi
Registration #4	2018-06-19	59.109 mi
Registration #5	2019-06-10	74.437 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		

More info >





### Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
0569	

# Safety ratings

Number of seats CarCheck.co.uk

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



Dimensions & weight	
Width	1837 mm
Height	1640 mm
Length	4365 mm
Wheel base	2613 mm
Kerb weight	1421 kg
Max. allowed weight	2030 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5

5

Number of axles	2
Engine number	JBER0146552