



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB P/V 130TDI
Colour	Blue
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	29.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-18
Pictures	18
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-01
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	21
Total items failed	3

MOT #18	2023-10-19 15:44
MOT test number	662420057879
Result	✓ Passed
Next expiry date	2024-11-01
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Central exhaust corroded
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #17	2023-10-17 15:00
MOT test number	244806703024
Result	✗ Failed
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))
MAJOR	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
Advice	Central exhaust corroded

**MOT #16** 2022-11-02 09:47**MOT test number** 597254565169**Result** ✓ Passed**Advice** Central Rear exhaust box outer casing corroded and coming off**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #15** 2022-11-02 09:47**MOT test number** 725150321936**Result** ✗ Failed**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Front Registration plate insecure (0.1 (a))**Advice** Central Rear exhaust box outer casing corroded and coming off**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2021-10-29 08:12**MOT test number** 107218094376**Result** ✓ Passed**MOT #13** 2021-06-17 13:53**MOT test number** 343358423535**Result** ✓ Passed**Minor** Front Suspension arm ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))**Advice** Offside Rear Nail in tyre**MOT #12** 2020-07-10 13:49**MOT test number** 744032529039**Result** ✓ Passed

**MOT #11** 2019-07-17 13:54**MOT test number** 917176788303**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2018-07-21 08:45**MOT test number** 500288068386**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2017-07-26 16:00**MOT test number** 637618134047**Result** ✓ Passed**MOT #8** 2017-07-26 16:00**MOT test number** 378207601972**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #7** 2016-07-20 08:14**MOT test number** 237784348387**Result** ✓ Passed**Advice** Front window screen cracked but not in drivers view



<b>MOT #6</b>	2015-07-13 10:12
<b>MOT test number</b>	697384095159
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2014-07-17 09:33
<b>MOT test number</b>	356408194187
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2013-07-20 11:32
<b>MOT test number</b>	578111203264
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2013-07-20 11:32
<b>MOT test number</b>	279041903236
<b>Result</b>	✗ Failed
<div><b>Pass with rectification</b> Registration plate lamp not working (1.1.C.1d)</div>	
<b>MOT #2</b>	2012-07-27 13:12
<b>MOT test number</b>	788569102222
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2011-07-29 17:30
<b>MOT test number</b>	897540111231
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
1 November 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		1 November 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>LP08ATY</b>
Plate since	2019-06-29
Current registration	<b>LP08ATY</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-31
Last registration	2023-10-19
Complete history	<a href="#">See info</a>



Registration #1	2008-07-31	6 mi
Registration #2	2011-07-29	37.850 mi
Registration #3	2012-07-27	45.452 mi
Registration #4	2013-07-20	52.711 mi
Registration #5	2014-07-17	60.340 mi
Registration #6	2015-07-13	66.476 mi
Registration #7	2016-07-20	73.462 mi
Registration #8	2017-07-26	81.010 mi
Registration #9	2017-07-26	81.010 mi
Registration #10	2018-07-21	86.630 mi
Registration #11	2019-05-20	91.277 mi
Registration #12	2019-05-20	91.277 mi
Registration #13	2019-05-20	91.277 mi
Registration #14	2019-05-20	91.277 mi
Registration #15	2019-05-20	91.277 mi
Registration #16	2019-05-20	91.277 mi
Registration #17	2019-05-20	91.277 mi
Registration #18	2019-05-20	91.277 mi
Registration #19	2019-05-20	91.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1969 mm
Length	4890 mm
Kerb weight	1872 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2

